


## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE





Co Reg No : 197701469G

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Sih Gek Hui Ann Mrs Ann Teo-Sih			
MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Reg No/Reg Date	SLW2842K / 05/02/201			
	Date In/Mileage				
	Chassis No	MMBSTA13AJH001033			
	Engine No	3A92UGP3340			
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT			
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK			

	Terms	Date/Time Printed	CSE	Operator	19101918	WIP No		TANA DA YES
80000XAX	Credit	28/12/2021/ 10:21	BLK	282 / Kevin Leong		19367		
75000000		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	/	(	9	0110				900 1800.00
REPLACE	FRT BUMPI	ER, FRT LH FENDER, SI	UPPORT & AF	FECTED AREA (0450				no inchas
E PNT98000							/	700 1050.00
	DRK ON FR	T BUMPER, FRT LH FEN	DER & FRT S	SUPPORT @350			1	7 120.00
E PNT88000	. THETALL	DADIATOD CONDENCED	FOD FACTUR	TATE DEDATE				/ . 120.00
A 55900099		RADIATOR, CONDENSER	FUK FACILI	TATE KEPAIK				/? 80.00
	UP AIRCON	CAS						- 00.00
M SUNDRY	or Alacon	uns						/ 40 88.00
	RUST PRE	VENTION						75.00
A 54900099			n 1				1000	/30.00
CHECK W	IRING & C	HASSIS ELECTRICAL, SY	STEM & > i		20	1		1
A 10028901		HASSIS ELECTRICAL SY	5111				11100	/120.00
TO CARR	Y OUT DIA	GNOSTIC CHECK ON ELE	CARONIC GO	ITROL SYSTEM CL	50	7	MALE	/
50110111								X117. 50.00
	LY FRT NU	MBER PLATE WITH FRAME	E .					. /
M SUNDRY								NO 90.00
SUNDRIE								
M EMDIEM	CCOL BI				1.00	17 00	00.00	17 00
M EMBLEM		101						
M HEADLAM	P ASSY, LH				1.00	663.00	23.00	510.51
M HEADLAM M LAMP AS	P ASSY, LH	IH YAN			1.00	663.00 305.00	23.00 23.00	510.51 234.85
M HEADLAM M LAMP AS M BRACKET	P ASSY,LH SY,FOG,FR FR BUMPE	LH ? KAA			1.00 1.00 1.00	663.00 305.00 13.00	23.00 23.00 23.00	510.51 234.85 10.01
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM	P ASSY,LH SY,FOG,FR ,FR BUMPE ,FR BUMPE ,SIDE,FR	CH ? AAA			1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00	23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE	IP ASSY,LH SY,FOG,FR ,FR BUMPE ,FR BUMPE ,SIDE,FR I	R, LH 7 KAA R, LH 3 KAA LH 7 KAA			1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00	23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET	IP ASSY,LH SY,FOG,FR ,FR BUMPE ,FR BUMPE ,SIDE,FR I FR UNDER ,FR BUMPE	CH ? KAA R, LH ? KAA CH ? KAA ? KAA R, RH? KAA			1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86 127.05
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET M COVER,HI	IP ASSY, LH SY, FOG, FR FR BUMPE FR BUMPE SIDE, FR I FR UNDER FR BUMPE EADLAMP SI	CH ZAA R, LH ZAA R, LH ZAA Z ZAA R, RH Z ZAA UPT PANEL X AA			1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00 13.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86 127.05
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET M COVER,HI M FACE ED	IP ASSY, LH SY, FOG, FR , FR BUMPE , FR BUMPE , SIDE, FR I FR UNDER , FR BUMPE EADLAMP SI	CH ? **  R, LH ? **  R, LH ? **  R, LH ? **  R, RH ? *  R, R			1.00 1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00 13.00 62.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86 127.05 10.01 47.74
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET M COVER,HI M FACE,FR M MARK,THI	IP ASSY, LH SY, FOG, FR FR BUMPE FR BUMPE FR UNDER FR BUMPE FR BUMPE EADLAMP SI BUMPER REF-DIA	CH ? YAA R, LH ? YAA R, LH ? YAA ? YAA R, RH ? YAA UPT PANEL X AA			1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00 13.00 62.00 706.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86 127.05 10.01 47.74 543.62
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET M COVER,HI M FACE,FR M MARK,THE M GRILLE,F	IP ASSY, LH SY, FOG, FR , FR BUMPE , FR BUMPE , SIDE, FR I FR UNDER , FR BUMPE EADLAMP SI BUMPER REE-DIA	R, LH ? KAA R, LH ? KAA R, LH ? KAA P, FAA R, RH ? KAA UPT PANEL X AA			1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00 13.00 62.00 706.00 70.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86 127.05 10.01 47.74 543.62 53.90
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET M COVER, HI M FACE, FR M MARK, THI M GRILLE, M FENDER,	IP ASSY, LH SY, FOG, FR , FR BUMPE , FR UNDER , FR BUMPEF EADLAMP SU BUMPER REE-DIA RADIATOR FR LH	CH ? KAA R, LH ? KAA R, LH ? KAA P, FAAA P, RH? KAA P, SH? KAA P, SH? KAA			1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00 13.00 62.00 706.00 70.00 557.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00	510.51 234.85 10.01 97.79 13.86 127.05 10.01 47.74 543.62 53.90 428.89
M HEADLAM M LAMP AS M BRACKET M GARNISH M AIR DAM M GRILLE, M BRACKET M COVER, HI M FACE, FR M MARK, THE M GRILLE, M FENDER, M PANEL AS	IP ASSY, LH SY, FOG, FR , FR BUMPE, , FR BUMPE, , FR BUMPER , FR B	CH ? KAA R, LH ? KAA R, LH ? KAA P, FAAA P, RH? KAA P, SH? KAA P, SH? KAA			1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	663.00 305.00 13.00 127.00 18.00 165.00 13.00 62.00 706.00 70.00	23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00 23.00	17.00 510.51 234.85 10.01 97.79 13.86 127.05 10.01 47.74 543.62 53.90 428.89 385.00 812.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other renair requiring the removal of the windscreen the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Sih Gek Hui Ann Mrs Ann Teo-Sih		
Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Reg No/Reg Date	SLW2842K / 05/02/201		
	Date In/Mileage			
	Chassis No	MMBSTA13AJH001033		
	Engine No	3A92UGP3340		
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT		
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK		

ccount No	Terms	Date/Time Printed	CSE	Operator	12/08/20	WIP No		
AX00008	Credit		BLK	282 / Kevin Leong		19367		
7503050	4900 VALUE	Description of Good	s / Services	Was Street Street	Qty	Unit Price		Amount
4 REINFORC	EMENT,FR	BUMPER Y. XAN			1.00	469.00	23.00	361.13
							2	
		巨	sti	ima	e			
		ci IRV	EYOR NAME	Passer - Hy good	nok8_			
		SUR\	E: 30 12	pre 1530	-5du	n <sup>s</sup>		
		REM £3	MARKS: — CCCS: THA Ros	PRIVERS Pair	+			
Confirm & a	accepted I	by			7% GST on	Ne 7074	ett .53	7,074.5 495.2
						tal Payal		7,569.7
						ILAI PAVA	916	/.509./

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.