

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3341X

2 FRONT FENDER SHIELD RH / LH @\$164.70 1 FRONT FENDER BLUE-DRIVE RH 1 FRONT WHEEL CAP RH 1 FRONT BUMPER 1 FRONT BUMPER MOULDING 1 FRONT BUMPER SIDE BRACKET RH 1 FRONT BUMPER LOWER GRILLE 1 FRONT BUMPER LOWER GRILLE 1 TO REPAIR SEE LABOUR 1 OUT SAN SEE LABOUR 1 FRONT BUMPER UPPER MOULDING 1 CUT SAN SEE LABOUR 26 CUT SAN SEE LABOUR 27 CUT SAN SEE LABOUR 28 CUT SAN SEE LABOUR 29 CUT SAN SEE LABOUR 29 CUT SAN SEE LABOUR 29 CUT SAN SEE LABOUR 20 CUT SAN SEE LABOUR 21 FRONT BUMPER LOWER GRILLE 22 CUT SAN SEE LABOUR 23 CUT SAN SEE LABOUR 26 CUT SAN SEE LABOUR 27 CUT SAN SEE LABOUR 28 CUT SAN SEE LABOUR 29 CUT SAN SEE LABOUR 20 CUT SAN SEE LABOUR 20 CUT SAN SEE LABOUR 21 FRONT BUMPER LOWER GRILLE 22 CUT SAN SEE LABOUR 23 CUT SAN SEE LABOUR 26 CUT SAN SEE LABOUR 27 CUT SAN SEE LABOUR 28 CUT SAN SEE LABOUR 29 CUT SAN SEE LABOUR 20 CUT SAN S	3.80 3.40 3.60 3.40 3.50 3.50	588.80 329.40 - - 430.90 368.50
2 FRONT FENDER SHIELD RH / LH @\$164.70 TORN 329 1 FRONT FENDER BLUE-DRIVE RH NOT NECESSARY 26 1 FRONT WHEEL CAP RH TO REPAIR SEE LABOUR 1 FRONT BUMPER DISTORTED 430 1 FRONT BUMPER UPPER MOULDING CUT 368 1 FRONT BUMPER SIDE BRACKET RH NOT NECESSARY 290 1 FRONT BUMPER LOWER GRILLE CUT 368	0.40 6.60 6.40 0.90 3.50 0.00	329.40 - - 430.90
1 FRONT FENDER BLUE-DRIVE RH 1 FRONT WHEEL CAP RH 2 TO REPAIR SEE LABOUR 1 FRONT BUMPER 1 FRONT BUMPER MOULDING 2 CUT 3 FRONT BUMPER SIDE BRACKET RH 3 FRONT BUMPER LOWER GRILLE 3 CUT	3.60 3.40 0.90 3.50 0.00	430.90
1 FRONT WHEEL CAP RH TO REPAIR SEE LABOUR 1 FRONT BUMPER DISTORTED 430 1 FRONT BUMPER UPPER MOULDING CUT 368 1 FRONT BUMPER SIDE BRACKET RH NOT NECESSARY 1 FRONT BUMPER LOWER GRILLE CUT 368	3.40 0.90 3.50 0.00	
LABOUR 1 FRONT BUMPER 1 FRONT BUMPER UPPER MOULDING 1 FRONT BUMPER SIDE BRACKET RH 1 FRONT BUMPER LOWER GRILLE CUT 368).90 3.50).00	
1 FRONT BUMPER UPPER MOULDING CUT 368 1 FRONT BUMPER SIDE BRACKET RH NOT NECESSARY 290 1 FRONT BUMPER LOWER GRILLE CUT 368	3.50	
1 FRONT BUMPER SIDE BRACKET RH NOT NECESSARY 290 1 FRONT BUMPER LOWER GRILLE CUT 368	0.00	368.50
1 FRONT BUMPER LOWER GRILLE CUT 368		-
	3.50	
A EDONT DUMBED OBJUTE DU		368.50
1 FRONT BUMPER GRILLE RH CUT 93	3.45	93.45
1 FOGLAMP RH NOT NECESSARY 642	2.50	-
1 HEADLAMP RH NOT NECESSARY 1,993	3.65	-
1 FRT BUMPER LIP (ADDITIONAL) CUT 186	3.90	186.90
1 RADIATOR GRILLE (ADDITIONAL) CRACKED 1,409).10	1,409.10
LESS 25% DISCOUNT -1,768	3.68	-943.89
5,306	5.02	2,831.66
SPECIAL NETT ITEMS		
1 FRT FENDER ADV. STICKER RH (SN) NECESSARY 100	0.00	60.00
100	0.00	60.00
LABOUR	十	
PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT WHEEL CAP RH.	0.00	420.00
SPRAY PAINTING - FRT BUMPER ETC. 600	0.00	500.00
CHECK WIRINGS. 40	0.00	20.00
TUFF KOTE. 40	0.00	30.00
WHEEL ALIGNMENT. NOT NECESSARY 120	0.00	-
TOWING FEE. 60	0.00	60.00
1,660	0.00	1,030.00
GRAND TOTAL 7,066	.02	3,921.66

Report Ref No. CS/SMO21013213/Utf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			3,921.66
-----------------------------	--	--	----------

Report Ref No. CS/SMO21013213/Utf3e2

CHUA KANG SENG

Licensed Appraiser