

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013215/UVY3N2**Date:** 13/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00124332103

**Claimant Vehicle
No :** SMJ198G**Insured
Vehicle No :** EG8333R

Date of Loss: 26/12/2021

Nature of Claim: TP

Claim
No: SNM21D207609/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMJ198G**

Make & Model: KIA CERATO, 1.6 LX (A)

Engine No: G4FGJH704838

Reg. Date: 20/02/2019 (Man. Year: 2018)

Chassis No: KNAF1416MK5014236

Colour: White

Odometer: 55307 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,520.00	1,081.00	1,439.00	57.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,670.00	1,210.00	42.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,400.00	2,751.00	2,649.00	49.06
+ GST 7.00/7.00% (S\$)	378.00	192.57	185.43	49.06
Nett Amount (S\$)	5,778.00	2,943.57	2,834.43	49.06

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 28/12/2021 Inspected At:

Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2022)
Parts:	143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ198G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ORNAMENT-KIA NO 1	Necessary	32.00 FS	*32.00 FS
2	1		*UPR COVER-FRONT BUMP	Deformed	633.00 FS	*633.00 FS
3	1		*LWR GRILLE-FRONT BUM	Grazed	262.00 FS	*262.00 FS
4	1		*FASTENER-BUMPER (10 Pcs)	Necessary (5 Pcs only)	40.00 FS	*20.00 FS
5	1		*LH SIDE BRACKET-FR B	Not Necessary	22.00 FS	*- FS
6	1		*RH SIDE BRACKET-FR B	Not Necessary	22.00 FS	*- FS
7	1		*RH MOULDING-FRONT BU	Not Necessary	36.00 FS	*- FS
8	1		*RH LAMP ASSY-SIDE RE	Not Necessary	143.00 FS	*- FS
9	1		*LH MOULDING-FRONT BU	Not Necessary	36.00 FS	*- FS
10	1		*LH LAMP ASSY-SIDE RE	Not Necessary	143.00 FS	*- FS
11	1		*RH LAMP ASSY-DAY RUN	Not Necessary	203.00 FS	*- FS
12	1		*LH LAMP ASSY-DAY RUN	Not Necessary	203.00 FS	*- FS
13	1		*ABSORBER-FRONT BUMPE	Torn	84.00 FS	*84.00 FS
14	1		*BEAM COMPLETE-FR BUM	Not Necessary	497.00 FS	*- FS
15	1		*LWR STIFFNER-FR BPR	Not Necessary	114.00 FS	*- FS
16	1		*FRONT LICENSE PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,520.00	1,081.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC/SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REPLACE LOGO,UPPER & LOWER FRONT BUMPER,CLIPS,BRACKETS,T/SIGNAL LAMP & COVER,DRL LAMP,ENERGY ABSORBER.REINFORCEMENT,ETC STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	1,280.00	640.00
4	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	1,100.00	550.00
5	CERAMIC COATING (OWNER PURCHASED)	New	150.00	150.00
Gross Labour Cost (\$\$)			2,880.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >