

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013216/KQY3N2**Date:** 28/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00107672102

Claimant Vehicle No : GW7777S **Insured Vehicle No :** GY3526R

Date of Loss: 23/12/2021 Nature of Claim: TP Claim No: SNM21D207550/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GW7777S**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 5L5306889

Reg. Date: 24/03/2003 (Man. Year: 2003) Chassis No: JTFUF34Y503000924

Colour: White Odometer: 304393 km

Engine Capacity: 2986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: Condor 9 mm Rear Left Side: Hankook 2/2 mm

Front Right Side: Condor 9 mm Rear Right Side: Hankook 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,026.25	2,345.80	3,680.45	61.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,330.00	1,120.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,476.25	3,675.80	4,800.45	56.63
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	8,476.25	2,800.00	5,676.25	66.97
+ GST 7.00/7.00% (\$\$)	593.34	196.00	397.34	66.97
Nett Amount (\$\$)	9,069.59	2,996.00	6,073.59	66.97

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 29/12/2021 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW7777S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	468.00 FL	*448.60 FL
2	1		*FRONT SIDE PANEL O/S	Bent	455.00 FL	*187.40 FL
3	1		*FRONT BUMPER	Bent	1,086.00 FL	*564.00 FL
4	2		*FRONT BUMPER SIDE BRACKET	Repair	292.00 FL	*- FL
5	2		*FRONT BUMPER TOP BRACKET	Repair	218.00 FL	*- FL
6	1		*FRONT DOOR INNER TRIM BOARD O/S	Serviceable	465.00 FL	*- FL
7	1		*FRONT PANEL LOWER GARNISH	Serviceable	275.00 FL	*- FL
8	1		*WING MIRROR ASSY O/S	Serviceable	248.00 FL	*- FL
9	1		*FRONT SIDE LAMP O/S	Broken	321.00 FL	*215.10 FL
10	1		*HEADLAMP O/S	Mtg Cracked	694.00 FL	*645.30 FL
11	1		*FRONT DOOR O/S	Bent	1,034.00 FL	*1,034.00 FL
12	2		*FRONT DOOR HINGE O/S	Repair	242.00 FL	*- FL
13	1		*QUARTER PANEL O/S	No such part	356.00 FL	*- FL
14	1		*FRONT DOOR WEATHERSTRIP O/S	Serviceable	186.00 FL	*- FL
15	1		*FRONT WINDSCREEN MOULDING	Serviceable	198.00 FL	*- FL
16	1		*FRONT DOOR WINDOW CHANNEL O/S	Serviceable	115.00 FL	*- FL
17	1		*FRONT DOOR STEP PANEL O/S	Repair	342.00 FL	*- FL
18	1		*CABIN WEATHERSTRIP O/S	Serviceable	217.00 FL	*- FL
19	1		*FRONT DOOR STEP GARNISH O/S	Serviceable	151.00 FL	*- FL
20	8		*FRONT GRILLE CLIPS	Not Necessary	44.00 FS	*- FS
21	6		*QUARTER PANEL CLIPS O/S	Not Necessary	33.00 FS	*- FS
22	10		*FRONT BUMPER RIVETS	Not Necessary	55.00 FS	*- FS
23	6		*FRONT DOOR STEP GARNISH CLIPS O/S	Not Necessary	33.00 FS	*- FS
24	8		*FRONT DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	44.00 FS	*- FS
25	1		*FRONT WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
26	1		*FRONT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
27	1		*FRONT DOOR COMPANY STICKER O/S	Necessary	25.00 FS	*25.00 FS
28	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,867.00	3,119.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,840.75	773.60
Total Parts (\$\$)	6,026.25	2,345.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	500.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	700.00
4	TO REMOVE AND REFIT O/S FRONT DOOR COMPONENTS TO REPLACE O/S FRONT DOOR,CHECK AND ALIGNMENT	New	100.00	60.00
5	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	50.00
Gross Labour Cost (\$\$)			2,450.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >