

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21013220/KQF3N2**Date:** 29/04/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29143941ACX
Claimant Vehicle No :	GBA5566Y	Insured Vehicle No :	YL3093C
Date of Loss:	27/12/2021	Nature of Claim:	TP
		Claim No:	639493

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA5566Y		
Make & Model:	VOLKSWAGEN CADDY TDI, 2.0 D DSG WGDR SIDE (M)	Engine No:	DFS016754
Reg. Date:	19/11/2020 (Man. Year: 2019)	Chassis No:	WV1ZZZ2KZLX024273
Colour:	Metallic Silver	Odometer:	17662 km
Engine Capacity:	1968 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,468.00	4,407.43	60.57	1.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,010.00	1,210.00	54.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	6,688.00	5,417.43	1,270.57	19.00

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	28/12/2021	Inspected At: A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650 Singapore 680113
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Apr 2022)	
Parts:	N/A	VOLKSWAGEN CADDY TDI 2.0 D DSG WGDR SIDE (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA5566Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	628.00 FL	*628.00 FL
2	1		*FRONT FENDER SIGNAL LAMP LH	Scratched	78.00 FL	*45.70 FL
3	1		*SIDE MIRROR LH	Mtg Broken	1,380.00 FL	*1,350.00 FL
4	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
5	1		*FRONT DOOR WINDOW OUTER MOULDING LH	Dented/Cut	169.00 FL	*169.00 FL
6	1		*FRONT DOOR WINDOW GLASS LH	Pinted	465.00 FL	*460.00 FL
7	1		*FRONT DOOR COMPANY INFO STICKER	Necessary	20.00 FS	*20.00 FS
8	1		*PRO OPTIMUM PPF WRAP-FENDER LH	Necessary	800.00 FS	*800.00 FS
9	1		*PRO OPTIMUM PPF WRAP-DOOR LH	Necessary	800.00 FS	*800.00 FS
10	1		*PRO OPTIMUM PPF WRAP-MIRROR COVER LH	Necessary	200.00 FS	*200.00 FS
11	1		*3M CRYSTALLINE SOLAR FILM-DOOR WINDOW GLASS LH	Necessary	200.00 FS	*200.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	4,740.00 4,672.70
					- List Item Discount on L Items 10.00/10.00% (\$\$)	272.00 265.27
					Total Parts (\$\$)	4,468.00 4,407.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	600.00	400.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	900.00	480.00
3	WIRING CHARGES	New	100.00	20.00
4	REMOVE/REFIX SIDE MIRROR }	New	120.00	80.00
5	REMOVE/REFIX FRONT DOOR WINDOW GLASS }	New	200.00	0.00
6	REMOVE/REFIX FRONT DOOR QUARTER GLASS }	New	120.00	0.00
7	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	180.00	30.00
Gross Labour Cost (\$\$)			2,220.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >