#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Christina Wong Date: 25 Mar 2022

# **Preliminary Advice**

Insured : YL3093C

Vehicle No

No

TP Vehicle : GBA5566Y Accident Date

: 27/12/2021

Make : VOLKSWAGEN CADDY TDI Assignment Date : 28/12/2021

Date of : 28/12/2021

Est. Duration of • 4

Inspection

Repair

Inspection At: A T AUTO CONSULTANT (HQ)

B/113 TECK WHYE LANE, #05-650

SINGAPORE 680113

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 6,688.00 **Revised Amount** :S\$ 5,417.43 Check Items (Estimated) :S\$ 0.00 Total :S\$ 5,417.43

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

(	)	The vehicle is economical for repair
(	)	The vehicle is not economical for repair
( X	)	Part-by-Part repair
(	)	Lump Sum repair

( X ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.