

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

SOMPO INSURANCE SINGAPORE PL  50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623  Code: SMO  1. Policy Particulars:- THIRD PARTY CLAIM  Insured Veh. SKQ 1799C  Veh. Inspected  SMQ 4975S  Policy No.  Coverage (\$)  0.00  Claim No.  CMTD2103850/THE  Excess (\$)  0.040/0004	Affiliated to Federation Internationale Des Experts En Automobile	
SINGAPORE LAND TOWERSINGAPORE 048623  Code: SMO  1. Policy Particulars:- THIRD PARTY CLAIM  Insured Veh. SKQ 1799C Veh. Inspected SMQ 4975S  Policy No. Coverage (\$) 0.00  Claim No. CMTD2103850/THE Excess (\$) 0.00	1/Aqf3e2	
1. Policy Particulars :- THIRD PARTY CLAIM  Insured Veh. SKQ 1799C Veh. Inspected SMQ 4975S  Policy No. Coverage (\$) 0.00  Claim No. CMTD2103850/THE Excess (\$) 0.00		
Insured Veh.   SKQ 1799C   Veh. Inspected   SMQ 4975S		
Policy No. Coverage (\$) 0.00  Claim No. CMTD2103850/THE Excess (\$) 0.00	1. Policy Particulars :- THIRD PARTY CLAIM	
Claim No.         CMTD2103850/THE         Excess (\$)         0.00		
And Francisco ODAGETEG		
Assign From GRACE TEO Assign Date 28/12/2021		
2. Vehicle Particulars & Condition		
Make & ModelMAZDA CX-5c.c2488		
Engine No. HIDDEN Year of Reg. 2015		
Chassis No. JM6KE1031F0281117 Colour BLACK		
Odometer 154125 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre         235/55 R19         MICHELIN         6 mm		
L/H Front Tyre 235/55 R19 MICHELIN 6 mm		
R/H Rear Tyre 235/55 R19 MICHELIN 6 mm		
L/H Rear Tyre 235/55 R19 MICHELIN 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 27/12/2021 Inspection Date 29/12/2021		
Survey held at KT MOTORWERK		
3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days		