



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2253Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	430.90	-
1	FRONT BUMPER SIDE BRACKET LH	NOT NECESSARY	35.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	FRONT FENDER CLUE-DRIVE LH	NECESSARY	26.60	26.60
1	FRONT WHEEL CAP LH	NOT NECESSARY	346.40	-
1	FRONT BUMPER GRILLE LH	NOT NECESSARY	93.45	-
	LESS 20% DISCOUNT		-308.63	-5.32
			1,234.52	21.28
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER LH.		400.00	350.00
	SPRAY PAINTING.		600.00	500.00
	TUFF KOTE.	NOT NECESSARY	40.00	-
			1,040.00	850.00
GRAND TOTAL			2,274.52	871.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				700.00

Report Ref No. NS/INC21013223/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.