

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013237/ATY3N2
Date: 15/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00202352101
Claimant Vehicle No :	SLA4432M	Insured Vehicle No :	SMV6275P
Date of Loss:	21/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207500/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA4432M	Engine No:	CZC507710
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Chassis No:	WAUZZZ8V4G1056445
Reg. Date:	29/02/2016 (Man. Year: 2015)	Odometer:	32085 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,959.00	2,136.20	8,822.80	80.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,872.00	3,972.00	9,900.00	71.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,831.00	6,108.20	18,722.80	75.40
+ GST 7.00/7.00% (S\$)	1,738.17	427.57	1,310.60	75.40
Nett Amount (S\$)	26,569.17	6,535.77	20,033.40	75.40

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	29/12/2021	Inspected At: 55 UBI ROAD 1 . SINGAPORE 408699 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Mar 2022)**Parts:** 144 AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLA4432M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,070.00 FS	*2,070.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	32.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	237.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	41.00 FS	*- FS
6	1		*TAIL LIGHT-RH	Not Necessary	877.00 FS	*- FS
7	1		*TAIL LIGHT TRIM-RH	Not Necessary	30.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION OUTER-RH	Damaged	67.00 FS	*66.20 FS
9	1		*REAR FENDER-RH	Repair	4,140.00 FS	*- FS
10	1		*REAR WINDSCREEN	Not Necessary	814.00 FS	*- FS
11	1		*QUARTER WINDOW	Not Necessary	570.00 FS	*- FS
12	2		*PRIMER	Not Necessary	40.00 FS	*- FS
13	1		*REAR WHEEL HOUSING LINER	Not Necessary	240.00 FS	*- FS
14	1		*REAR WHEEL SPOILER-RH	Not Necessary	35.00 FS	*- FS
15	1		*REAR WHEEL SPOILER COVER-RH	Not Necessary	4.00 FS	*- FS
16	1		*FUEL FILLER	Not Necessary	89.00 FS	*- FS
17	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	*- FS
18	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
19	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
20	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
22	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,959.00	2,136.20
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	600.00	0.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT,INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENTS TRIMS.DISLODGE LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
7	TO DISMANTLE AND RENEW REAR BUMPER.TO CUT OUT AND WELD RHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,900.00	2,100.00
8	TO RESPRAY REAR BUMPER,RHS REAR FENDER,RHS SILL PANEL,DRAIN CHANNEL,DOOR ENTRANCE ROOF CHANNEL AND REAR END PANELLING	New	4,500.00	1,400.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	13,872.00
				3,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >