

Your Ref: S1M03N9D

Date: 04<sup>th</sup> Mar 2022

Our Ref: CS1/ASM21013242/Tes3e2

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Oh Vale

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PA 922U  
INSURED VEHICLE: SHA 9539D  
ACCIDENT DATE: 29/11/2021**

We thank you for your instruction on 28/12/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PA 922U from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles PA 922U and SHA 9539D.
- c) Colour damaged vehicle photographs of PA 922U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PA 922U
Make & Model	: Toyota Hiace Commuter GL 3.0A
Chassis Number	: KDH2230025768
Year of Registration	: 2015
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.