24 Penshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Reign Transport Services

Date

: 7 January 2022

C/o: Teamwork Garage Pte Ltd

Our ref

: TWG/12/2101/TP

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park, Singapore 408934

Accident Date

: 29 November 2021

Type of Survey: Third Party

Inspection Date

: 28 December 2021

Repairer Name

: Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park, Singapore 408934

PARTICULARS OF VEHICLE

Registration No : PA 922 U

Year / Capacity:

2015 / 2982 cc

Make / Model

: Toyota Hiace

Colour

Blue

Chassis No

: KDH2230025768

Mileage

448658

Engine No

: 1KD2560346

CONDITION OF TYRES

		Make	Size	Thread Balance	Rim
Front Nearside	:	Bridgestone	195 R15	5 mm	Normal
Front Offside	:	Bridgestone	195 R15	5 mm	Normal
Rear Nearside	:	Bridgestone	195 R15	5 mm	Normal
Rear Offside	:	Bridgestone	195 R15	5 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s portion.

(Details refer to the photographs attached)

Enclosed number of photographs:

99

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$9,800.00 on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.



Vehicle Registration No.: PA 922 U Our Ref N	No.: TWG/12/2101/TP
--	---------------------

0+-	Ot Desired		7	Repairer's Estimate		Revised		
Qty	Description	Conditions				Amount		
	SPARE PARTS - LIST ITEMS							
1	Front bumper	Damage	\$	628.65	\$	628.65		
1	Front bumper n/s retainer	Necessary	\$	157.08	\$	157.08 97		
1	Front n/s headlamp	Damage	\$	1,780.20	\$	1,780.20 1200		
1	Front n/s step garnish	Damage	\$	178.09	\$	178.09		
1	Front n/s step panel	Repair	\$	59.84		XR		
1	Front n/s door	Damage	\$	1,795.80	\$	1,795.80 1611		
2	Front n/s door hinges	Intact	\$	95.50		XNN		
1	Front n/s door checker	Intact	\$	86.50		XNN		
1	Front n/s fender inner shield	Damage	\$	208.56	\$	208.56		
1	N/s centre pillar	Damage	\$	747.56	\$	747.56		
1	Front n/s shock absorber	Damage	\$	303.00	\$	303.00 190.80		
1	Front n/s knuckle arm	Intact	\$	653.00		XNN		
1	Front n/s wheel hub with bearing	Damage	\$	403.70	\$	403.70 366.10		
1	Front n/s sliding door	Damage	\$	2,107.71	\$	2,107.71 XR		
1	Front n/s sliding door roller	Intact	\$	367.29				
1	Front n/s sliding door weatherstrip	Necessary	\$	424.38	\$	424.38 XNN		
1	Front n/s sliding door glass moulding	Necessary	\$	297.11	\$	297.11 XNN		
1	Rear n/s fender	Damage	\$	1,701.59	\$	1,701.59 XR		
			\$	11,995.56	\$	10,733.43 5227.46		
		Less 25%	\$	2,998.89	\$	2,683.36 3920.60		
	Total Cost - List Items		\$	8,996.67	\$	8,050.07		
	SPECIAL NETT ITEMS							
1	Sticker	Necessary	\$	80.00	\$	80.00 50		
1	Front n/s rim cover	Damage	\$	250.00	\$	250.00 180		
1	Rear n/s rim cover	Damage	\$	250.00	\$	250.00 180		
1	Front bumper clip (1 set)	Necessary	\$	60.00	\$	60.00 30		
1	Front fender inner shield clip (1 set)	Necessary	\$	30.00	\$	30.00 20		
1	Front sliding door sealant	Necessary	\$	150.00	\$	50.00 XNN		
	Total Cost - Special Nett items		\$	820.00	\$	720.00 460		

Total cost of parts

\$ 9,816.67	\$ 8,770.07



Vehicle Registration No.: PA 922 U

Our Ref No.:

TWG/12/2101/TP

S/No	Description		Repairer's Estimate		Revised Amount
	Total cost of parts c/f	\$	9,816.67	\$	8,770.07
	<u>LABOUR</u>				
1	To check wiring, lighting and resetting headlamps focusing.	\$	60.00	S	50.00 30
2	To remove and refit front undercarriage.	\$	150.00	\$	150.00
3	To conduct wheel alignment.	\$	200.00	\$	120.00 80
4	To remove and refit front doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$	200.00	\$	120.00 60
5	To remove and refit sliding doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$	200.00	\$	120.00 60
6	To apply undercoating on repaired and replaced panel.	\$	150.00	\$	120.00 60
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	2,000.00	\$	1,500.00 1200
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,800.00	\$	1,320.00 1200
					2840
	GRAND TOTAL	\$	14,576.67	\$	12,270.07
					7220.60 L/S\$5750 8 DAYS

Vehicle Registration No.: PA 922 U

Our Ref No.:

TWG/12/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 9,800.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser





















































































































































































