



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 6120J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	995.00	995.00
1	FRONT BUMPER O/S SIDE RETAINER	BENT	65.00	65.00
1	FRONT BUMPER N/S SIDE RETAINER	NOT NECESSARY	65.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	580.00	-
1	FRONT O/S FENDER	DENTED	685.00	685.00
1	FRONT O/S FENDER INNER SHIELD	TORN	260.00	260.00
1	FRONT O/S FENDER WHEEL HOUSING	TO REPAIR SEE LABOUR	655.00	-
1	FRONT O/S FENDER SIGNAL LAMP	CRACKED	85.00	85.00
1	O/S HEADLAMP	CRACKED	1,150.00	1,150.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	785.00	-
1	FRONT O/S LOWER ARM	BENT	765.00	765.00
1	FRONT O/S KNUCKLE ARM	BENT	745.00	745.00
1	FRONT O/S WHEEL BEARING	DAMAGED	195.00	195.00
1	FRONT O/S DRIVE SHAFT	NOT NECESSARY	1,225.00	-
1	WIPER TANK	DEFORMED	295.00	295.00
	LESS 10% DISCOUNT		-855.00	-524.00
			7,695.00	4,716.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT O/S SPORT WHEEL (SN) (50%)	DENTED	600.00	300.00
1	SET FRONT SPORT SHOCK ABSORBER ASSY (SN)	NOT NECESSARY	1,200.00	-
1	FRONT O/S TYRE (SN)	SERVICEABLE	350.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET FRONT O/S FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	45.00
			2,240.00	390.00
<b><u>LABOUR</u></b>				
	TO CHECK AND RE-ADJUST COMPUTERISED WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS AND COMPONENTS.		300.00	150.00

Report Ref No. CS1/LPM21013243/Uvf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISCONNECT AND CHECK FRONT ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. TO REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		60.00	40.00
	TO APPLY RUSTPROOFING, RESEAL TUFF-COATING TREATMENT TO FRONT REPLACED / REPAIRED PARTS AND PANELS.		100.00	30.00
	TO PUTTY AND SPRAY PAINTING ON FRONT DAMAGED PORTION INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		1,200.00	600.00
	TO REMOVE AND REPLACE DAMAGED PARTS AND PANELS. TO CUT, WELD, STRAIGHTEN AND PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT O/S FENDER WHEEL HOUSING AND FRONT SUPPORT PANEL.		1,200.00	500.00
			2,980.00	1,400.00
	<b>GRAND TOTAL</b>		<b>12,915.00</b>	<b>6,506.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,200.00</b>

Report Ref No. CS1/LPM21013243/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.