

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013247/UGA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800098355-02
Claimant Vehicle No :	SDQ1868U	Insured Vehicle No :	SMD4612H
Date of Loss:	24/12/2021	Nature of Claim:	TP
		Claim No:	2618401177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDQ1868U	Engine No:	R18A11026611
Make & Model:	HONDA CIVIC, 1.8 (A)	Chassis No:	JHMFD16206S207763
Reg. Date:	15/05/2006 (Man. Year: 2006)	Odometer:	395783 km
Colour:	Brown		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,752.08	1,355.12	4,396.96	76.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	1,170.00	1,520.00	56.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,442.08	2,525.12	5,916.96	70.09
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	8,442.08	2,000.00	6,442.08	76.31
+ Loss of Use (5.0 x S\$80.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,407.45		

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	29/12/2021	Inspected At: Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt Singapore 428586
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Dented / Deformed	780.80 FL	*698.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	318.10 FL	*- FL
3	1		*FRONT BUMPER LEFT RETAINER	Not Necessary	51.80 FL	*- FL
4	1		*FRONT BUMPER LEFT BRACKET	Not Necessary	48.80 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	223.50 FL	*- FL
6	1		*FRONT LEFT FOG LAMP GARNISH	Not Necessary	88.80 FL	*- FL
7	1		*FRONT BONNET ASSY	Repair	990.60 FL	*- FL
8	1		*FRONT GRILLE ASSY	Not Necessary	224.10 FL	*- FL
9	1		*FRONT GRILLE CHROME	Not Necessary	165.10 FL	*- FL
10	1		*FRONT GRILLE CENTRE LOGO	Not Necessary	68.60 FL	*- FL
11	1		*FRONT LEFT HEADLAMP	Cracked	912.20 FL	*894.80 FL
12	1		*FRONT LEFT HEADLAMP MODULE	No such part	680.30 FL	*- FL
13	1		*FRONT LEFT HEADLAMP BRACKET	Bent	38.50 FL	*38.50 FL
14	1		*FRONT SUPPORT PANEL ASSY	Repair	483.20 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	172.40 FL	*- FL
16	2		*FRONT SUPPORT PANEL SIDE GARNISH	Not Necessary	110.50 FL	*- FL
17	2		*FRONT SUPPORT PANEL RUBBER STOPPER	Not Necessary	38.80 FL	*- FL
18	2		*FRONT HORN	Not Necessary	108.10 FL	*- FL
19	1		*FRONT LEFT FENDER	Repair	867.50 FL	*- FL
20	1		*FRONT LEFT FENDER INNER COWLING	Not Necessary	108.90 FL	*- FL
21	1		*FRONT LEFT FENDER LAMP	Not Necessary	96.50 FL	*- FL
22	1		*FRONT BRACE PANEL	Not Necessary	175.50 FL	*- FL
23	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
24	6		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
25	4		*FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
26	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
27	1		*SET FRONT SUPPORT PANEL SIDE GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*FRONT NO PLATE	Not Necessary	100.00 FS	*- FS
29	6		*FRONT LEFT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,102.60	1,681.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,350.52	326.28
Total Parts (\$\$)	5,752.08	1,355.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS	New	1,200.00	500.00
2	TO PUTTY AND SPRAY PAINTING FRONT LEFT PORTION	New	1,200.00	650.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	20.00
4	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	140.00	0.00
5	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$)			2,690.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >