



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 2507Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	1,655.00	-
1	FRONT RH DOOR WEATHERSTRIPE	NOT NECESSARY	202.00	-
1	REAR RH DOOR	DENTED	1,741.00	1,741.00
1	REAR RH DOOR WEATHERSTRIPE	NECESSARY	214.00	214.00
1	REAR RH DOOR OUTER HANDLE	TO REPAIR SEE LABOUR	196.00	-
1	ROCKER PANEL OUTER GARNISH RH	NOT NECESSARY	585.00	-
	LESS 10% DISCOUNT		-	-195.50
			4,593.00	1,759.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR AND REAR RH DOOR OUTER HANDLE.		700.00	450.00
	SPRAY PAINTING.		700.00	700.00
	WIRING.		50.00	30.00
	TO TRANSFER FRONT AND REAR DOOR FITTINGS.		300.00	80.00
			1,750.00	1,260.00
GRAND TOTAL			6,343.00	3,019.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/AGI21013250/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.