

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21013251/TVY3M4**Date:** 30/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00068522101

**Claimant Vehicle No :** GBL6689L **Insured Vehicle No :** GBB5327R

Date of Loss: 23/12/2021 Nature of Claim: TP Claim No: SNM21D207562/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBL6689L**

Make & Model: NISSAN NP300 NAVARA, 2.3 D (M) Engine No: YS23341721A

Reg. Date: 26/07/2017 (Man. Year: 2016) Chassis No: MNTCB4D23Z0000088

Colour: Orange Odometer: 90323 km

Engine Capacity: 2298 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 255/70R16 Rear Tyre Size: 255/70R16

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,431.50	3,964.00	9,467.50	70.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	1,450.00	3,360.00	69.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,241.50</b>	<b>5,414.00</b>	<b>12,827.50</b>	<b>70.32</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,300.00</b>		
<b>(\$\$)</b>	18,241.50	4,300.00	13,941.50	76.43
<b>+ GST 7.00/7.00% (\$\$)</b>	1,276.91	301.00	975.91	76.43
<b>Nett Amount (\$\$)</b>	<b>19,518.41</b>	<b>4,601.00</b>	<b>14,917.41</b>	<b>76.43</b>

**INSPECTION**

Date of Assignment: 04/01/2022

Date Inspected: 28/12/2021 Inspected At: AP Automotive Services Pte Ltd  
56 Loyang Way, #04-04 Loyang Enterprise Building  
Singapore 508775

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 May 2022)	
<b>Parts:</b>	N/A	NISSAN NP300 NAVARA 2.3 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL6689L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	740.00 FL	*540.00 FL
2	1		*REAR BUMPER TOP STEP GARNISH	Deformed	890.00 FL	*350.00 FL
3	1		*REAR BUMPER CENTER BUTTOM	Deformed	320.00 FL	*220.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	870.00 FL	*670.00 FL
5	1		*REAR NUMBER PLATE LAMP LH	Distorted	210.00 FL	*100.00 FL
6	2		*REAR BUMPER BRACKET	Repair	780.00 FL	*- FL
7	1		*TAIL GATE	Bent	1,394.00 FL	*1,100.00 FL
8	2		*TAIL GATE INNER LOCK	Not Necessary	514.00 FL	*- FL
9	2		*TAIL GATE LOCK CATCH	Not Necessary	130.00 FL	*- FL
10	2		*TAIL GATE HINGE	Repair	188.00 FL	*- FL
11	1		*TAIL GATE INNER TRIM COVER	Not Necessary	794.00 FL	*- FL
12	1		*TAIL GATE LOGO	Necessary	85.00 FL	*65.00 FL
13	1		*TAIL GATE EMBLEM <E>	Necessary	25.00 FL	*25.00 FL
14	1		*TAIL GATE EMBLEM (NP300 I)	Necessary	75.00 FL	*55.00 FL
15	1		*TAIL GATE EMBKE (NAVARA)	Necessary	125.00 FL	*75.00 FL
16	2		*TAIL LAMP LH	Cracked (1pc only)	700.00 FL	*350.00 FL
17	1		*TAIL GATETOP TIRM	Not Necessary	280.00 FL	*- FL
18	1		*TAIL GATE TOP MOLDING	Not Necessary	430.00 FL	*- FL
19	1		*REAR SIDE PANEL RH	Not Necessary	2,390.00 FL	*- FL
20	1		*REAR CARGO BED END PANEL	Repair	1,210.00 FL	*- FL
21	2		*REVERSE SENSOR HOLDER	Distorted	90.00 FL	*60.00 FL
22	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	385.00 FL	*- FL
23	1		*REVERSE CAMERA	Necessary	801.00 FS	*250.00 FS
24	2		*REVERSE SENSOR	Necessary	288.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE	Bent	80.00 FS	*45.00 FS
26	1		*REAR BUMPER TOP STEP GARNISH CLIP (SET)	Necessary	80.00 FS	*20.00 FS
27	1		*REAR CARGO BED FROOL BROAD WOODEN	Cracked	550.00 FS	*200.00 FS
28	1		*REAR SIDE PANEL RH SEALANT	Not Necessary	150.00 FS	*- FS
29	1		*REAR CARGO BED END PANEL SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,694.00</b>	<b>4,325.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,262.50	361.00
<b>Total Parts (\$\$)</b>	<b>13,431.50</b>	<b>3,964.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVING AND REPLACING PARTS.	New	1,800.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	1,600.00	600.00
3	TUFF COAT.	New	80.00	30.00
4	WIRING, BULB CHECKING.	New	180.00	30.00
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	350.00	60.00
6	CONDUCT WATER TER LEAKAGE TEST.	New	80.00	0.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	30.00
8	REMOVE AND REFIX FUEL TANK TO FACILITATE REPLACEMENT.	New	80.00	0.00
9	REMOVE AND REFIX REAR AIR TANK.	New	380.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>4,810.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >