

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013253/AVY3N2**Date:** 25/02/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00111222101

Claimant Vehicle No : SLT8811B**Insured Vehicle No :** GBE1739X

Date of Loss: 27/12/2021

Nature of Claim: TP

Claim No: SNM21D207627/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT8811B**

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A)

Engine No: G4FGHU629216

Reg. Date: 29/09/2017 (Man. Year: 2017)

Chassis No: KMHD841CMJU533646

Colour: Gold

Odometer: 86742 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,968.04	4,628.65	3,339.39	41.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,915.00	1,810.00	2,105.00	53.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,883.04	6,438.65	5,444.39	45.82
Approved Total (Overridden) (\$\$)		5,100.00		
(\$\$)	11,883.04	5,100.00	6,783.04	57.08
+ GST 7.00/7.00% (\$\$)	831.81	357.00	474.81	57.08
Nett Amount (\$\$)	12,714.85	5,457.00	7,257.85	57.08

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 29/12/2021 Inspected At:

SK Automobile Pte Ltd (HQ)
23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection
Centre
Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8811B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,526.00 FL	*1,526.00 FL
2	1		*FRONT BONNET MECHANISM LOCK	Not Necessary	129.90 FL	*- FL
3	4		*FRONT BONNET RUBBER GUIDE STOPPER	Not Necessary	40.40 FL	*- FL
4	1		*FRONT HEADLAMP LH/RH	O/s Cracked	2,399.60 FL	*1,198.80 FL
5	1		*FRONT HEADLAMP LOWER BRACKET LH/RH	O/s Cracked	197.20 FL	*98.60 FL
6	1		*FRONT FENDER RH	Dented	1,227.70 FL	*1,227.70 FL
7	1		*FRONT FENDER INNER SHIELD LH/RH	O/s Torn	171.40 FL	*85.70 FL
8	1		*FRONT BUMPER	Distorted	474.40 FL	*474.40 FL
9	1		*FRONT BUMPER LOWER RUBBER LIP	Not Necessary	61.73 FL	*- FL
10	1		*FRONT BUMPER TOP RUBBER SEAL (STICK ON)	Not Necessary	65.30 FL	*- FL
11	2		*FRONT BUMPER INNER AIR DUCT LH/RH	Not Necessary	39.40 FL	*- FL
12	2		*FRONT BUMPER FOG LAMP COVER LH/RH	Not Necessary	290.60 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	695.80 FL	*- FL
14	1		*FRONT BUMPER INNER SPONGE	Not Necessary	110.50 FL	*- FL
15	1		*FRONT BUMPER LOWER BEAM	Not Necessary	81.00 FL	*- FL
16	1		*FRONT BUMPER SIDE RETAINER LH/RH	O/s Damaged	87.22 FL	*43.61 FL
17	2		*FRONT BUMPER CORNER RETAINER LH/RH	Not Necessary	173.40 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Cracked	949.30 FL	*949.30 FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	179.50 FL	*- FL
20	1		*WASHER TANK	Deformed	55.30 FL	*55.30 FL
21	1		*WASHER TANK MOTOR	Not Necessary	64.10 FL	*- FL
22	1		*AIRCON CONDENSER AIR GUIDE LH/RH	O/s Cracked	77.80 FL	*38.90 FL
23	1		*SET FRONT BONNET INSULATOR MAT CLIPS	Not Necessary	50.00 FS	*- FS
24	2		*FRONT FENDER INNER SHIELD CLIPS SET LH/RH	Necessary	120.00 FS	*30.00 FS
25	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*SET FRONT BUMPER RIVET	Not Necessary	60.00 FS	*- FS
27	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
28	2		*AIRCON CONDENSER AIR GUIDE CLIPS SET LH/RH	Necessary	60.00 FS	*10.00 FS
29	1		*FRONT WHEEL HUP CAP RH	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,787.55	5,768.31
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,819.51	1,139.66
Total Parts (\$\$)	7,968.04	4,628.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,600.00	1,000.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,400.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	105.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	120.00	30.00
5	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	0.00
6	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	0.00
7	TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	New	120.00	60.00
8	TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	New	120.00	60.00
Gross Labour Cost (\$\$)			3,915.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >