

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013255/UVY3N2**Date:** 18/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00048112101		
Claimant Vehicle No :	SLM5999A	Insured Vehicle No :	GBG292M		
Date of Loss:	27/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207624/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM5999A		
Make & Model:	MERCEDES-BENZ E200 (R18), 2.0 (A)	Engine No:	27492030786349
Reg. Date:	29/03/2017 (Man. Year: 2016)	Chassis No:	WDD2130422A085467
Colour:	White	Odometer:	89597 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,131.02	15,439.01	19,692.01	56.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	2,070.00	1,300.00	38.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	38,501.02	17,509.01	20,992.01	54.52
Approved Total (Overridden) (\$\$)		14,000.00		
Nett Amount (\$\$)	38,501.02	14,000.00	24,501.02	63.64

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	28/12/2021 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2022)
Parts:	143	MERCEDES-BENZ E200 (R18) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM5999A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent/Warped	3,886.21 F	*2,392.33 FL
2	2		*BONNET HINGES	Repair	490.00 F	*- FL
3	2		*BONNET ACTUATORS	Activated	850.00 F	*610.00 FL
4	1		*FRONT BUMPER	Distorted	2,650.00 F	*1,516.35 FL
5	1		*FRONT BUMPER SPONGE	Torn	233.80 F	*182.40 FL
6	1		*FRONT BUMPER BEAM	Bent	815.00 F	*755.32 FL
7	1		*FRONT BUMPER SIDE RETAINER N/S	Distorted	245.00 F	*105.60 FL
8	1		*FRONT BUMPER FOG LAMP COVER N/S	Twisted	185.00 F	*166.00 FL
9	1		*FRONT BUMPER FOG LAMP CHROME N/S	Cracked	155.00 F	*155.00 FL
10	2		*FRONT BUMPER PDC SENSORS	Shorted	490.00 F	*370.00 FL
11	4		*FRONT BUMPER PDC SENSOR HOLDERS	Necessary	80.00 F	*80.00 FL
12	1		*FRONT BUMPER UNDER COVER	Torn	495.10 F	*488.21 FL
13	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*FRONT BUMPER INNER RETAINER	Twisted	288.10 F	*265.00 FL
15	1		*FRONT BUMPER CENTRE GRILLE	Torn	182.50 F	*166.01 FL
16	1		*FRONT GRILLE	Cracked	1,388.20 F	*1,052.05 FL
17	1		*HEADLAMP N/S	Broken	6,850.21 F	*3,520.82 FL
18	1		*HEADLAMP TOP PANEL N/S	Repair	285.10 F	*- FL
19	1		*FRONT FENDER N/S	Buckled	1,215.00 F	*1,042.16 FL
20	1		*FRONT FENDER INNER SHIELD N/S	Torn	388.90 F	*288.50 FL
21	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
22	1		*FRONT FENDER INNER N/S	Repair	755.10 F	*- FL
23	1		*FRONT DOOR N/S	Repair	3,821.00 F	*- FL
24	1		*FRONT DOOR LOWER CHROME N/S	Not Necessary	205.00 F	*- FL
25	1		*FRONT SUPPORT PANEL	Repair	645.00 F	*- FL
26	1		*FRONT SHOCK ABSORBER N/S	Serviceable	1,200.50 F	*- FL
27	1		*FRONT KNUCKLE ARM N/S	Bent	1,155.80 F	*1,005.35 FL
28	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	650.00 F	*615.00 FL
29	1		*FRONT LOWER ARM N/S	Twisted	611.20 F	*488.50 FL
30	1		*FRONT TOP ARM N/S	Bent	425.10 F	*425.00 FL
31	1		*FRONT TORSION ARM N/S	Twisted	688.20 F	*411.00 FL
32	1		*FRONT SPORT RIM N/S	Warped	1,300.00 F	*893.86 FL
33	1		*FRONT TYRE N/S	Serviceable	250.00 F	*- FL
34	1		*CONDENSER	Not Necessary	1,018.00 F	*- FL
35	1		*RADIATOR	Not Necessary	1,005.00 F	*- FL
36	1		*FRONT FENDER LOWER CHROME N/S	Necessary	128.00 F	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	35,131.02	17,154.46
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,715.45
Total Parts (\$\$)	35,131.02	15,439.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	200.00	150.00
4	TO REFILL AIR CON GAS	New	100.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	100.00
6	TO RESET & REPROGRAMME SYSTEM	New	160.00	100.00
7	TO SPRAY RUST PROOFING	New	80.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,080.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	980.00
Gross Labour Cost (S\$)			3,370.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >