

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21013258/DPS3Q2**Date:** 16/12/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SHD3952S	Insured Vehicle No :	SMV9314R
Date of Loss:	24/12/2021	Nature of Claim:	TP
		Claim No:	MFL2022D0000017

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3952S	Engine No:	G4LEJU046906
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVJU103599
Reg. Date:	12/07/2018 (Man. Year: 2018)	Odometer:	422372 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	DURATURN 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	DURATURN 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,695.59	9,392.34	3,303.25	26.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,940.00	1,560.00	3,380.00	68.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,635.59	10,952.34	6,683.25	37.90
Approved Total (Overridden) (S\$)		9,850.00		
(S\$)	17,635.59	9,850.00	7,785.59	44.15
+ GST 7.00/7.00% (S\$)	1,234.49	689.50	544.99	44.15
Nett Amount (S\$)	18,870.08	10,539.50	8,330.58	44.15
+ Loss of Use (12.0 x S\$40.00/day) (S\$)		480.00		
+ Car Rental (12.0 x S\$125.19/day) (S\$)		1,502.28		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		12,609.23		
Global Sum Settlement (S\$)		11,800.00		

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	29/12/2021 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2022)
Parts:	143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3952S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR (LH)	Dented	1,797.20 FL	*1,797.20 FL
2	1		*FRT DOOR RUBBER	Necessary	250.00 FL	*250.00 FL
3	1		*FRONT DOOR REGULATOR (LH)	Mtg Broken	750.40 FL	*367.84 FL
4	1		*FRONT DOOR POWER MOTOR ,LH	Not Necessary	689.20 FL	*- FL
5	1		*FRONT DOOR INNER LOCK (LH)	Damaged	385.60 FL	*385.60 FL
6	1		*FRONT DOOR OUTER HANDLE (LH)	Repair	234.80 FL	*- FL
7	1		*FRONT DOOR MIRROR ASSY (LH)	Not Necessary	1,691.70 FL	*- FL
8	1		*FRONT DOOR TRIM BOARD (LH)	Mtg Broken	796.80 FL	*796.80 FL
9	1		*FRONT DOOR PROTECTOR (LH)	Bent / Cut	186.20 FL	*186.20 FL
10	1		*REAR DOOR (LH)	Dented	1,789.90 FL	*1,789.90 FL
11	1		*REAR DOOR RUBBER (LH)	Necessary	280.00 FL	*280.00 FL
12	1		*REAR DOOR OUTER HANDLE (LH)	Not Necessary	124.80 FL	*- FL
13	1		*REAR DOOR GEAR REGULATOR (LH)	Mtg Broken	367.84 FL	*367.84 FL
14	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	256.80 FL	*- FL
15	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
16	1		*REAR DOOR HINGE UPPER (LH)	Not Necessary	173.88 FL	*- FL
17	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	170.50 FL	*- FL
18	1		*REAR DOOR CHECK (LH)	Not Necessary	85.92 FL	*- FL
19	1		*REAR DOOR TRIM BOARD (LH)	Mtg Broken	613.60 FL	*613.60 FL
20	1		*REAR DOOR PROTECTOR (LH)	Cut / Necessary	166.20 FL	*166.20 FL
21	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	3,764.90 FL	*3,764.90 FL
22	1		*ROCKER PANEL OUTER GARNISH	Cut	715.60 FL	*715.60 FL
23	1		*ROCKER PANEL OUTER GARNISH CLIP	Necessary	65.00 FL	*65.00 FL
24	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
25	1		*REAR DOOR TEL NO STICKER (LH)	Not fitted	10.00 FS	*- FS
26	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,828.24	11,701.68
- List Item Discount on L Items 20.00/20.00% (\$)	3,132.65	2,309.34
Total Parts (\$)	12,695.59	9,392.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,600.00	700.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	0.00
7	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
8	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
9	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
10	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			4,940.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >