6/9/22, 1:17 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21013260/AGA3Q2

Date: 09/06/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle SMG5516E Insured Vehicle No: SLG5704R

No: SINGSSTOE INSURED VEHICLE NO. SEGSTOAN

Date of Loss: 26/12/2021 Nature of Claim: TP Claim No: MFL2021D0005649

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG5516E

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK073943

Reg. Date: 24/12/2018 (Man. Year: 2018) Chassis No: WAUZZZF55KA013468

Colour: Red Odometer: 37002 km

Engine Capacity: 1984 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,218.00	3,742.50	1,475.50	28.28
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,752.00	2,152.00	600.00	21.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,970.00	5,894.50	2,075.50	26.04
	+ GST 7.00/7.00% (S\$)	557.90	412.62	145.28	26.04
	Nett Amount (S\$)	8,527.90	6,307.12	2,220.78	26.04
		0400 00/1 \ \ (04)	0.40.00		

+ Loss of Use (3.0 x S\$80.00/day) (S\$) 240.00

Nett Liability (S\$) 6,547.12

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/9/22, 1:17 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 May 2022)

Parts: 143 AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SMG5516E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,504.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	165.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	223.00 FS	*222.50 FS
4	1		*REAR BUMPER CHROME TRIM	Cut	1,016.00 FS	*1,016.00 FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	940.00 FS	*- FS
7	2		*REAR BUMPER SEAL	Not Necessary	28.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	46.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*- FS
10	4		*REAR PARKING AID SENSOR RING	Not Necessary	14.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Fra	nchise	part. S=Spc	Nett.			
				Total Parts (S\$)	5,218.00	3,742.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
<u>Lab</u>	our Items					
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00		
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00		
3	TO RESPRAY REAR BUMPER	New	1,000.00	800.00		
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00		
	Gross Labou	r Cost (S\$)	2,752.00	2,152.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >