

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21013264/R1QF3E2

Date: 22/02/2022

REFERENCE

Insured/Claimant: KAMARUDDIN BIN MD SAHABUDIN
Date of Loss: 28/12/2021

Policy No: 1900250683
Nature of Claim: OD Claim No: 0268632887SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ5987B**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UHX6365
Reg. Date: 26/11/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH002532
Colour: Maroon Odometer: 206759 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,893.32	6,711.37	1,181.95	14.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,890.00	5,110.00	1,780.00	25.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,783.32	11,821.37	2,961.95	20.04
- Excess (S\$)	900.00	900.00	0.00	0.00
(S\$)	13,883.32	10,921.37	2,961.95	21.33
+ GST 7.00/7.00% (S\$)	971.83	764.50	207.33	21.33
Nett Amount (S\$)	14,855.15	11,685.87	3,169.28	21.33

INSPECTION

Date of Assignment: 29/12/2021

Date Inspected: 29/12/2021 Inspected At:

Estimated Period of Repair: 9.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Deformed	706.00 FL	*706.00 FL
4	5		*CLIP, FR BUMPER	Necessary	20.00 FL	*20.00 FL
5	1		*COVER, HEADLAMP SUPT PANEL	Cracked	62.00 FL	*62.00 FL
6	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
7	1		*BRACKET, FR BUMPER, RH	Cracked	13.00 FL	*13.00 FL
8	1		*GRILLE, FR UNDER	Scratched	165.00 FL	*165.00 FL
9	1		*GARNISH, FR BUMPER, LH	Cut	127.00 FL	*127.00 FL
10	1		*GARNISH, FR BUMPER, RH	Cracked	127.00 FL	*127.00 FL
11	1		*TOW COVER, FR BUMPER	Cut	13.00 FL	*13.00 FL
12	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
13	1		*GRILLE, RADIATOR	Cracked	557.00 FL	*557.00 FL
14	1		*HOOD	Buckled	737.00 FL	*737.00 FL
15	1		*HINGE, HOOD, LH	Not Necessary	56.00 FL	*- FL
16	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
17	1		*INSULATOR, HOOD	Deformed	177.00 FL	*177.00 FL
18	6		*CLIP, HOOD INSULATOR	Necessary	18.00 FL	*18.00 FL
19	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
20	1		*FENDER, FR LH	Repair	500.00 FL	*- FL
21	1		*FENDER, FR RH	Buckled	500.00 FL	*500.00 FL
22	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	98.00 FL	*- FL
23	1		*SHIELD, FR WHEELHOUSE, RH	Not Necessary	98.00 FL	*- FL
24	12		*CLIP, INNERSHIELD	Necessary	48.00 FL	*48.00 FL
25	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
26	1		*PANEL, HEADLAMPS SUPPORT, UPR	Bent	66.00 FL	*66.00 FL
27	1		*HEADLAMP ASSY, LH	Cracked	663.00 FL	*663.00 FL
28	1		*HEADLAMP ASSY, RH	Cracked	663.00 FL	*663.00 FL
29	1		*LAMP ASSY, FOG, FR LH	Not Necessary	305.00 FL	*- FL
30	1		*LAMP ASSY, FOG, FR LH	Not Necessary	305.00 FL	*- FL
31	1		*GARNISH, FR PILLAR, LH	Not Necessary	30.00 FL	*- FL
32	1		*GARNISH, FR PILLAR, RH	Cracked	30.00 FL	*30.00 FL
33	2		*GARNISH, FR FENDER	Not Necessary	130.00 FL	*- FL
34	1		*CONDENSER ASSY, A/C REFRIGE	Bent	762.00 FL	*762.00 FL
35	1		*PANEL, AIR GUIDE	Cracked	112.00 FL	*112.00 FL
36	1		*RADIATOR ASSY	Bent	972.00 FL	*972.00 FL
37	1		*FAN, COOLING	Cracked	77.00 FL	*77.00 FL
38	1		*SHROUD, COOLING FAN	Cracked	131.00 FL	*131.00 FL
39	1		*MOTOR, COOLING FAN	Shorted	484.00 FL	*484.00 FL
40	1		*TANK, WINDSHIELD WASHER	Deformed	75.00 FL	*75.00 FL
41	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
42	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,220.00	8,685.00
- List Item Discount on L Items 23.00/23.00% (\$)	2,326.68	1,973.63
Total Parts (\$)	7,893.32	6,711.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER, FR SUPPORT, BONNET, LHF FENDER & RHF FENDER. REPAIR LHF A PILLAR, RHF A PILLAR & RHF DOOR	New	3,150.00	1,800.00
2	RESPRAY FR BUMPER, FR SUPPORT, BONNET, LHF FENDER, RHF FENDER LHF A PILLAR, RHF A PILLAR & RHF DOOR	New	2,800.00	2,450.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AC GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
8	SUPPLY BODY PNL SEALANT	New	80.00	40.00
9	REPAIR FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
Gross Labour Cost (\$\$)			6,890.00	5,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >