

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21013265/R1VF3E2

Date: 09/05/2022

REFERENCE

Insured/Claimant: HO CHOON SING (HE JUNXING) Policy No: 1900163290-01
Date of Loss: 19/11/2021 Nature of Claim: OD Claim No: 5151512645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP2230B**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UHX6019
Reg. Date: 17/09/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH002502
Colour: Red Odometer: 46168 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$68,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,196.47	4,099.28	1,097.19	21.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,330.00	5,310.00	4,020.00	43.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,526.47	9,409.28	5,117.19	35.23
+ GST 7.00/7.00% (S\$)	1,016.85	658.65	358.20	35.23
Nett Amount (S\$)	15,543.32	10,067.93	5,475.39	35.23

INSPECTION

Date of Assignment: 29/12/2021

Date Inspected: 29/12/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
2	1		*FACE, RR BUMPER	Cracked	751.00 FL	*751.00 FL
3	1		*BRACKET, RR BUMPER, LH	Cracked	28.00 FL	*28.00 FL
4	1		*BRACKET, RR BUMPER, RH	Not Necessary	28.00 FL	*- FL
5	4		*CLIP, RR BUMPER	Necessary	16.00 FL	*16.00 FL
6	1		*PANEL, QTR, OTR LH	Buckled	759.00 FL	*759.00 FL
7	1		*PANEL, RR COMB LAMP HSG, LH	Bent	60.00 FL	*60.00 FL
8	1		*EXTN, QTR PANEL, UPR OTR LH	Not Necessary	118.00 FL	*- FL
9	1		*PANEL, RR END	Bent	427.00 FL	*427.00 FL
10	1		*MUD GUARD, RR LH	Missing	41.00 FL	*41.00 FL
11	1		*SHIELD, RR WHEELHOUSE, LH	Not Necessary	40.00 FL	*- FL
12	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
13	3		*SPACER, RR WINDOW	Necessary	27.00 FL	*27.00 FL
14	1		*PANEL, TRUNK LID	Bent	795.00 FL	*795.00 FL
15	1		*WEATHERSTRIP, TRUNK LID	Not Necessary	157.00 FL	*- FL
16	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 FL	*- FL
17	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 FL	*- FL
18	1		*LATCH, TRUNK LID	Not Necessary	218.00 FL	*- FL
19	1		*STRIKER, TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
20	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
21	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
22	1		*REFLECTOR LH	Not Necessary	23.00 FL	*- FL
23	1		*LAMP ASSY, COMB, RR LH	Not Necessary	337.00 FL	*- FL
24	1		*UNPAINTED BODYKITS	Cracked	1,643.00 FS	*1,643.00 FS
25	1		*DECAL, MIVEC	Necessary	36.00 FL	*36.00 FL
26	1		*CLIP, RR END TRIM (4 PCS) (Supplementary)	Necessary	12.00 FL	*12.00 FL
27	1		*GROMMET, RR END TRIM (4 PCS) (Supplementary)	Necessary	12.00 FL	*12.00 FL
28	1		*GROMMET, TAIL LAMP (2 PCS) (Supplementary)	Necessary	6.00 FL	*6.00 FL
29	1		*GROMMET, TAIL LAMP (2 PCS) (Supplementary)	Necessary	3.00 FL	*3.00 FL
30	1		*CAP, TAIL LAMP (Supplementary)	Necessary	3.00 FL	*3.00 FL
31	1		*BUZZER, KEYLESS OPERATION, RR (Supplementary)	Cracked	91.00 FL	*91.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,234.00	4,827.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,037.53	727.72
Total Parts (\$\$)	5,196.47	4,099.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW LHR FENDER, RR BUMPER, RR END PNL & BOOTLID. REPAIR RR FLR PNL	New	3,800.00	2,250.00
2	RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER & RHR FENDER	New	3,850.00	1,925.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT	New	120.00	120.00
5	REMOVE & REFIT FUEL TANK ASSY	New	300.00	225.00
6	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	REMOVE & REFIT RR WINDSCREEN GLASS	New	300.00	240.00
9	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
10	SUPPLY RR NUMBER PLATE WITH CASING	New	80.00	0.00
11	REMOVE & REFIT REVERSE SENSOR	New	100.00	80.00
12	SUPPLY REVERSE SENSOR	New	220.00	0.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
14	SUPPLY BODY PNL SEALANT	New	80.00	40.00
15	SUPPLY C&C BADGE	New	50.00	40.00
			Gross Labour Cost (\$)	9,330.00
				5,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >