



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Mr Ho Choon Sing (he Junxing)
	Reg No/Reg Date	SMP2230B / 17/09/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AKH002502
	Engine No	3A92UHX6019
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 11:21	TLE	261 / Edwin Caina	17724

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHR FENDER , RR BUMPER , RR END PNL & BOOTLID @450 X 5 REPAIR RR FLR PNL X				2250 3800.00
E PNT98000 RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL , RR FLR PNL , BOOTLID , LHR FENDER & RHR FENDER @350 X 5.5				1925 3850.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT				120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM , CAREPET & SEAT				120.00
A 13900099 REMOVE & REFIT FUEL TANK ASSY				225 300.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS				240 300.00
M SUNDRY SUPPLY WINDSCREEN SEALANT				80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				nn X 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				80 100.00
M SUNDRY SUPPLY REVERSE SENSOR				Xm 220.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40 80.00
M SUNDRY SUPPLY BODY PNL SEALANT				40 80.00
M SUNDRY SUPPLY C&C BADGE				40 50.00
M SUNDRY				20 80.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		Cust No/Name	/Mr Ho Choon Sing (he Junxing)
		Reg No/Reg Date	SMP2230B / 17/09/201
		Date In/Mileage	/ 0
		Chassis No	MMBSTA13AKH002502
		Engine No	3A92UHX6019
		Make/Model	MIT/19MY ATTRAGE 1.2 CVT
		Colour/Trim	P01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 11:21	TLE	261 / Edwin Caina	17724

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Sundries				
M FACE,RR BUMPER <i>cm</i>	1.00	751.00	23.00	578.27
M BRACKET,RR BUMPER,LH <i>?cm</i>	1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH <i>?XAN</i>	1.00	28.00	23.00	21.56
M CLIP,RR BUMPER <i>re</i>	4.00	4.00	23.00	12.32
M PANEL,QTR,OTR LH <i>bu</i>	1.00	759.00	23.00	584.43
M PANEL,RR COMB LAMP HSG,LH <i>?st</i>	1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR LH <i>?XAN</i>	1.00	118.00	23.00	90.86
M PANEL,RR END <i>photo</i>	1.00	427.00	23.00	328.79
M MUD GUARD,RR LH <i>mis</i>	1.00	41.00	23.00	31.57
M SHIELD,RR WHEELHOUSE,LH <i>?XAN</i>	1.00	40.00	23.00	30.80
M STOPPER,WINDSHIELD GLASS <i>?XAN</i>	1.00	3.00	23.00	4.62
M SPACER,RR WINDOW <i>?XAN</i>	3.00	9.00	23.00	20.79
M PANEL,TRUNK LID <i>?XAN</i>	1.00	795.00	23.00	612.15
M WEATHERSTRIP,TRUNK LID <i>?XAN</i>	1.00	157.00	23.00	120.89
M HINGE,TRUNK LID,LH <i>?XAN</i>	1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH <i>?XAN</i>	1.00	203.00	23.00	156.31
M LATCH,TRUNK LID <i>?XAN</i>	1.00	218.00	23.00	167.86
M STRIKER,TRUNK LID LATCH <i>?XAN</i>	1.00	20.00	23.00	15.40
M MARK,THREE-DIA <i>re</i>	1.00	70.00	23.00	53.90
M MARK,ATTRAGE <i>?XAN</i>	1.00	21.00	23.00	16.17
M REFLECTOR LH <i>?XAN</i>	1.00	23.00	23.00	17.71
M LAMP ASSY,COMB,RR LH <i>?XAN</i>	1.00	337.00	23.00	259.49
M UNPAINTED BODYKITS <i>cm</i>	1.00	1643.00	20.00	1314.40
M DECAL,MIVEC <i>re</i>	1.00	36.00	23.00	27.72

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

SURVEYOR NAME: Rajan - Ho 90510068

SURVEYOR SIGNATURE: [Signature]

DATE: 29/12/21 @ 12:10

REMARKS: 10 days

Confirm & accepted by	<u>Rajan/Excess: TBA</u>	Nett	14,100.08
	<u>Resy before paint</u>	7% GST on	14100.08
		Total Payable	15,087.09
Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.