

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013268/AVCN2**Date:** 23/04/2022**REFERENCE**

Insured/Claimant:	JIANG HUI	Policy No:	2100237541	Claim No:	2889574464SG
Date of Loss:	22/12/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ3770K	Engine No:	BPJ200482
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4F6AN073939
Reg. Date:	19/11/2010 (Man. Year: 2010)	Odometer:	240030 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$38,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,767.00	6,370.88	5,396.12	45.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,332.00	3,182.00	2,150.00	40.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,099.00	9,552.88	7,546.12	44.13
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	16,299.00	8,752.88	7,546.12	46.30
+ GST 7.00/7.00% (S\$)	1,140.93	612.70	528.23	46.30
Nett Amount (S\$)	17,439.93	9,365.58	8,074.35	46.30

INSPECTION

Date of Assignment:	29/12/2021		
Date Inspected:	28/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,506.00 FS	*2,004.80 FS
2	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	892.00 FS	*- FS
3	2		*FRONT BUMPER BRACKET-LH/RH	Not Necessary	482.00 FS	*- FS
4	2		*FRONT BUMPER DISTANCE PIECE-LH & RH	Not Necessary	27.00 FS	*- FS
5	2		*FRONT BUMPER COMPENSATING PIECE	Not Necessary	46.00 FS	*- FS
6	1		*FRONT BUMPER COVER BRACKET-LH/RH/UPPER	O/s Cracked	70.00 FS	*27.28 FS
7	4		*FRONT BUMPER PULL STRAP-LOWER CENTER	Not Necessary	138.00 FS	*- FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	236.00 FS	*- FS
9	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	106.00 FS	*- FS
10	1		*FRONT BUMPER LICENCE PLATE TRIM	Deformed	195.00 FS	*156.00 FS
11	2		*FRONT BUMPER TRIM STRIP-LH/RH	Not Necessary	618.00 FS	*- FS
12	1		*FRONT BUMPER GRILLE COVER	Not Necessary	113.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIR COND STICKER	Not Necessary	30.00 FS	*- FS
15	1		*RADIATOR GRILLE	Cracked	816.00 FS	*652.40 FS
16	1		*HEADLIGHT-RH	Cut	3,252.00 FS	*2,601.60 FS
17	1		*FOG LAMP-RH	Not Necessary	364.00 FS	*- FS
18	1		*LIFT CYLINDER NOZZLE CARRIER-RH	Not Necessary	274.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE	Not Necessary	191.00 FS	*- FS
20	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
21	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
22	1		*AIRCON CONDENSER (Supplementary)	Dented	829.00 FS	*662.80 FS
23	1		*VALVE (Supplementary)	Necessary	52.00 FS	*41.60 FS
24	1		*PRESSURE SENDER (Supplementary)	Necessary	206.00 FS	*164.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

11,767.00

6,370.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.TO REPAIR BONNET.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND RENEW AIRCON CONDENSER. TO CARRY OUT PRESSURISE, VACUUM AND REGAS (Supplementary)	New	780.00	780.00
Gross Labour Cost (\$)			5,332.00	3,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >