

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013271/AVCE2

Date: 10/03/2022

REFERENCE

Insured/Claimant:	TAN SENG SOON	Policy No:	2070179457		
Date of Loss:	17/12/2021	Nature of Claim:	OD	Claim No:	8729578743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1770Z		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM026664
Reg. Date:	29/12/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF40MA011296
Colour:	White	Odometer:	28918 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$163,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,785.00	1,533.20	13,251.80	89.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,072.00	1,722.00	1,350.00	43.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,857.00	3,255.20	14,601.80	81.77
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	17,307.00	2,705.20	14,601.80	84.37
+ GST 7.00/7.00% (S\$)	1,211.49	189.36	1,022.13	84.37
Nett Amount (S\$)	18,518.49	2,894.56	15,623.93	84.37

INSPECTION

Date of Assignment:	29/12/2021		
Date Inspected:	28/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,233.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	358.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Cracked	262.00 FS	*209.20 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	44.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	135.00 FS	*- FS
8	1		*FRONT BUMPER TRIM - LH	Not Necessary	48.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,580.00 FS	*1,264.00 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	189.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIR COND STICKER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
17	4		*POP RIVET	Not Necessary	4.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	0.00 FS	*- FS
19	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
20	1		*HEADLIGHT - LH	Not Necessary	7,685.00 FS	*- FS
21	1		*LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
22	1		*LIFT CYLINDER CORRUGATED PIPE (NPA)	Not Necessary	0.00 FS	*- FS
23	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
24	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
25	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	Not Necessary	262.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,785.00 1,533.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,072.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >