

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21013272/GVF3N2**Date:** 13/06/2022**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MPC21A00013400
Claimant Vehicle No :	SCL3939Z	Insured Vehicle No :	SLL6569G
Date of Loss:	27/12/2021	Nature of Claim:	TP
		Claim No:	DMPC2100467H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCL3939Z	Engine No:	20544640S65B40A
Make & Model:	BMW M3, 3.0 (A)	Chassis No:	WBSWD92010P389215
Reg. Date:	24/05/2010 (Man. Year: 2009)	Odometer:	0 km
Colour:	White		
Engine Capacity:	3999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,970.96	0.00	17,970.96	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,000.00	3,900.00	79.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	22,870.96	1,000.00	21,870.96	95.63

INSPECTION

Date of Assignment:	29/12/2021	SR AUTOWORKS PTE LTD (HQ)
Date Inspected:	30/12/2021 Inspected At:	8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit #02-24
Estimated Period of Repair:	2.0 days	Singapore 415875

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2022)
Parts:	M1-COUPE	BMW M3 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCL3939Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,854.00 FL	*- FL
2	1		*FRONT BUMPER TOP RUBBER	Not Necessary	178.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	220.00 FL	*- FL
4	1		*FRONT BUMPER SPRAY NOZZLE RH	Not Necessary	198.10 FL	*- FL
5	1		*FRONT BUMPER SPRAY NOZZLE COVER RH	Not Necessary	78.90 FL	*- FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	75.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	217.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	542.00 FL	*- FL
9	1		*FRONT BUMPER SIDE AIR ARCH RH	Not Necessary	355.40 FL	*- FL
10	1		*FRONT BUMPER UNDER COVER	Not Necessary	355.40 FL	*- FL
11	2		*FRONT PARKING SENSOR RH	Not Necessary	712.00 FL	*- FL
12	2		*FRONT PARKING SENSOR SEAL RH	Not Necessary	40.80 FL	*- FL
13	1		*FRONT PARKING SENSOR WIRE HARNESS	Not Necessary	977.50 FL	*- FL
14	1		*HEAD LAMP RH	Not Necessary	2,388.10 FL	*- FL
15	1		*HEAD LAMP BALLASH RH	Not Necessary	216.00 FL	*- FL
16	1		*HEAD LAMP BOTTOM BRACKET RH	Not Necessary	279.40 FL	*- FL
17	1		*FRONT FENDER RH	Repair	969.70 FL	*- FL
18	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	456.00 FL	*- FL
19	1		*FRONT FENDER BRACKET RH	Not Necessary	108.70 FL	*- FL
20	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	330.50 FL	*- FL
21	1		*FRONT ABSORBER RH	Not Necessary	753.70 FL	*- FL
22	1		*FRONT LOWER ARM RH	Not Necessary	454.60 FL	*- FL
23	1		*FRONT CONTROL ARM RH	Not Necessary	444.50 FL	*- FL
24	1		*FRONT KNUCKLE ARM RH	Not Necessary	614.20 FL	*- FL
25	1		*FRONT WHEEL BEARING RH	Not Necessary	555.20 FL	*- FL
26	1		*SET FRONT BUMPER CLIP	Not Necessary	75.00 FS	*- FS
27	1		*SET FRONT BUMPER CARBON DIFFUSER	Not Necessary	2,000.00 FS	*- FS
28	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	90.00 FS	*- FS
29	1		*FRONT RIM RH	Repair	2,500.00 FS	*- FS
30	1		*FRONT TYRE RH	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,639.70	0.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	668.74	0.00
Total Parts (\$\$)	17,970.96	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,600.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	WIRING,BULB CHECKING	New	150.00	0.00
4	REFOCUS HEADLAMP BEAM	New	250.00	0.00
5	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
6	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS,PERFORM DISTANCE SENSORY INPUT TESTING	New	300.00	0.00
7	TO REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	800.00	0.00
8	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (\$\$)			4,900.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >