

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21013274/R1TF3N2**Date:** 04/01/2022**REFERENCE**

Insured/Claimant: RASHIDAH BINTE ALLAPITCHAY MOHAMAD Policy No: MPC21P00150000
Date of Loss: 24/12/2021 Nature of Claim: OD Claim No: DMPC2100474H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR3584A**
Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B4532761
Reg. Date: 11/08/2017 (Man. Year: 2017) Chassis No: JHMRU1810GX202759
Colour: Black Odometer: 64953 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$63,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	764.50	764.50	0.00	0.00
Miscellaneous Items	50.00	30.00	20.00	40.00
Labour	500.00	300.00	200.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,314.50	1,094.50	220.00	16.74
+ GST 7.00/7.00% (S\$)	92.02	76.62	15.40	16.74
Nett Amount (S\$)	1,406.52	1,171.12	235.40	16.74

INSPECTION

Date of Assignment: 29/12/2021

Date Inspected: 30/12/2021 Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jan 2022)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3584A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Rear windscreen (WCP)	Cracked	450.00 F	*450.00 F	
2	1		*Rear windscreen moulding @\$20*4 (WCP)	Necessary	80.00 F	*80.00 F	
3	1		*Boot lid outer garnish with logo badge (WCP)	Cracked	165.00 F	*165.00 F	
					Sub Total (\$\$)	695.00	695.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	69.50	69.50
					Total Parts (\$\$)	764.50	764.50

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Rear windscreen sealant (Necessary)	50.00	30.00
Sub Total (\$\$)			50.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	200.00	100.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	200.00	100.00
3	To remove and replace rear windscreen	New	100.00	100.00
Gross Labour Cost (\$\$)			500.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >