

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21013275/UTF3E2

Date: 14/01/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001824171		
Claimant Vehicle No :	SMG2822R	Insured Vehicle No :	SMY7591D		
Date of Loss:	27/12/2021	Nature of Claim:	TP	Claim No:	267519

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2822R		
Make & Model:	PEUGEOT 308, 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)	Engine No:	10XTA40963036
Reg. Date:	13/12/2018 (Man. Year: 2018)	Chassis No:	VF3LPHNYWJS089855
Colour:	Grey	Odometer:	53992 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,697.60	1,804.50	4,893.10	73.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	830.00	2,950.00	78.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,477.60	2,634.50	7,843.10	74.86
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	10,477.60	2,100.00	8,377.60	79.96

INSPECTION

Date of Assignment:	29/12/2021		
Date Inspected:	29/12/2021	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jan 2022)

Parts: 144 PEUGEOT 308 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG2822R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	85.00 FL	*- FL
2	1		*REAR TAILGATE	Not Necessary	1,450.00 FL	*- FL
3	1		*REAR TAILGATE INNER LOCK	Not Necessary	245.00 FL	*- FL
4	1		*REAR TAILGATE LOGO	Not Necessary	85.00 FL	*- FL
5	1		*REAR TAILGATE RUBBER	Not Necessary	146.00 FL	*- FL
6	1		*REAR TAILGATE PEUGEOT EMBLEM	Not Necessary	68.00 FL	*- FL
7	1		*REAR TAILGATE 308 EMBLEM	Not Necessary	65.00 FL	*- FL
8	2		*REAR TAILLAMP	Not Necessary	1,172.00 FL	*- FL
9	1		*REAR END PANEL	Repair	865.00 FL	*- FL
10	1		*REAR END PANEL INNER GARNISH	Not Necessary	192.00 FL	*- FL
11	1		*REAR END PANEL AIR VENT	Not Necessary	42.00 FL	*- FL
12	1		*REAR BUMPER	Dented / Warped	1,065.00 FL	*945.00 FL
13	2		*REAR BUMPER BRACKETS	Not Necessary	156.00 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	60.00 FL	*50.00 FL
15	1		*REAR BUMPER LOWER DIFFUSER	Deformed	425.00 FL	*425.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	685.00 FL	*585.00 FL
17	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 FL	*- FL
18	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.00 FL	*- FL
19	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
20	1		*SET REAR REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,394.00	2,005.00
- List Item Discount on L Items 10.00/10.00% (\$)	696.40	200.50
Total Parts (\$)	6,697.60	1,804.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO APPLY UNDERCOATING	New	200.00	0.00
7	PANEL BEATING	New	1,500.00	300.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	400.00
Gross Labour Cost (\$\$)			3,780.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >