

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21013278/TGA3Q2**Date:** 02/08/2022REFERENCE

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100479510-05 |
| <b>Claimant Vehicle No :</b> | GBH4914X                             | <b>Insured Vehicle No :</b> | SLF4302D      |
| Date of Loss:                | 23/12/2021                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 1922152091SG  |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBH4914X</b>                   | Engine No:  | K9KF646D517983    |
| Make & Model:               | NISSAN NV200, 1.5 (A)             | Chassis No: | VSKYBAM20U0153673 |
| Reg. Date:                  | 20/06/2018 (Man. Year: 2017)      | Odometer:   | 107166 km         |
| Colour:                     | Silver                            |             |                   |
| Engine Capacity:            | 1461 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 165 R14       | Rear Tyre Size:  | 165 R14       |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                          | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                          | 17,523.28         | 3,789.56          | 13,733.72         | 78.37         |
| Miscellaneous Items                            | 0.00              | 0.00              | 0.00              |               |
| Labour                                         | 5,480.00          | 1,280.00          | 4,200.00          | 76.64         |
| Paintwork Labour                               | 0.00              | 0.00              | 0.00              |               |
| Towing                                         | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>            | <b>23,003.28</b>  | <b>5,069.56</b>   | <b>17,933.72</b>  | <b>77.96</b>  |
| <b>Approved Total (Overridden) (S\$)</b>       |                   | <b>4,000.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                       | <b>23,003.28</b>  | <b>4,000.00</b>   | <b>19,003.28</b>  | <b>82.61</b>  |
| <b>+ Car Rental (7.0 x S\$80.00/day) (S\$)</b> |                   | 560.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                  |                   | 31.00             |                   |               |
| <b>Nett Liability (S\$)</b>                    |                   | <b>4,591.00</b>   |                   |               |

INSPECTION

|                             |                          |                                                    |
|-----------------------------|--------------------------|----------------------------------------------------|
| Date of Assignment:         | 29/12/2021               | SR AUTOWORKS PTE LTD (HQ)                          |
| Date Inspected:             | 29/12/2021 Inspected At: | 8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit #02-24 |
| Estimated Period of Repair: | 5.0 days                 | Singapore 415875                                   |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *TAILGATE LH                    | Bent          | 1,684.00 FL | *1,469.60 FL |
| 2   | 1   |          | *TAILGATE LOGO                  | Necessary     | 89.00 FL    | *89.00 FL    |
| 3   | 1   |          | *TAILGATE STICKER (NV200)       | Necessary     | 97.80 FL    | *97.80 FL    |
| 4   | 2   |          | *TAILGATE HINGE LH              | Repair        | 240.00 FL   | *- FL        |
| 5   | 1   |          | *TAILGATE CHECKER LH            | Repair        | 135.40 FL   | *- FL        |
| 6   | 1   |          | *TAILGATE OUTER GARNISH LH      | Not Necessary | 345.00 FL   | *- FL        |
| 7   | 2   |          | *TAILGATE NUMBER PLATE LAMP     | Not Necessary | 180.00 FL   | *- FL        |
| 8   | 1   |          | *TAILGATE OPENER HANDLE LH      | Not Necessary | 124.90 FL   | *- FL        |
| 9   | 1   |          | *TAILGATE LOWER LOCK LH         | Not Necessary | 415.40 FL   | *- FL        |
| 10  | 1   |          | *TAILGATE LOWER LOCK CATCH LH   | Not Necessary | 89.00 FL    | *- FL        |
| 11  | 1   |          | *TAILGATE LOCK MECHANISM LH     | Not Necessary | 357.10 FL   | *- FL        |
| 12  | 1   |          | *TAILGATE INNER BOARD LH        | Not Necessary | 445.90 FL   | *- FL        |
| 13  | 1   |          | *TAILGATE GLASS INNER SEAL LH   | Necessary     | 50.00 FL    | *50.00 FL    |
| 14  | 1   |          | *TAILGATE FRAIM WEATHERSTRIP    | Torn          | 255.60 FL   | *215.00 FL   |
| 15  | 1   |          | *REVERSE CAMERA                 | Not Necessary | 1,458.00 FL | *- FL        |
| 16  | 1   |          | *TAILGATE RH                    | Bent          | 1,093.00 FL | *1,093.00 FL |
| 17  | 2   |          | *TAILGATE HINGE RH              | Not Necessary | 240.00 FL   | *- FL        |
| 18  | 1   |          | *TAILGATE SIDE OPENER HANDLE RH | Not Necessary | 109.80 FL   | *- FL        |
| 19  | 1   |          | *TAILGATE LOWER LOCK RH         | Not Necessary | 415.40 FL   | *- FL        |
| 20  | 1   |          | *TAILGATE LOWER LOCK CATCH RH   | Not Necessary | 89.00 FL    | *- FL        |
| 21  | 1   |          | *TAILGATE INNER BOARD RH        | Not Necessary | 299.00 FL   | *- FL        |
| 22  | 1   |          | *TAILGATE WEATHERSTRIP RH       | Not Necessary | 245.70 FL   | *- FL        |
| 23  | 1   |          | *TAILGATE SIDE RUBBER           | Not Necessary | 127.30 FL   | *- FL        |
| 24  | 1   |          | *TAILGATE GLASS INNER SEAL RH   | Necessary     | 50.00 FL    | *50.00 FL    |
| 25  | 2   |          | *TAIL LAMP                      | Not Necessary | 578.00 FL   | *- FL        |
| 26  | 1   |          | *REAR BUMPER                    | Deformed      | 489.00 FL   | *489.00 FL   |
| 27  | 1   |          | *REAR BUMPER SPONGE             | Cracked       | 135.00 FL   | *135.00 FL   |
| 28  | 1   |          | *REAR BUMPER SIDE RETAINER      | Not Necessary | 88.90 FL    | *- FL        |
| 29  | 2   |          | *REAR BUMPER REFLECTOR          | Not Necessary | 254.00 FL   | *- FL        |
| 30  | 4   |          | *REAR BUMPER BOTTOM BRACKET     | Not Necessary | 224.00 FL   | *- FL        |
| 31  | 1   |          | *REAR BUMPER TOW COVER          | Not Necessary | 45.00 FL    | *- FL        |
| 32  | 1   |          | *REAR END PANEL (INNER)         | Repair        | 879.00 FL   | *- FL        |
| 33  | 1   |          | *REAR END PANEL (OUTER)         | Repair        | 258.00 FL   | *- FL        |
| 34  | 1   |          | *REAR END PANEL TOP GARNISH     | Not Necessary | 125.00 FL   | *- FL        |
| 35  | 1   |          | *REAR FLOOR PANEL               | Repair        | 1,564.00 FL | *- FL        |
| 36  | 1   |          | *REAR SPARE TYRE HOLDER BRACKET | Not Necessary | 548.00 FL   | *- FL        |
| 37  | 1   |          | *REAR SPARE TYRE HOLDER BOLT    | Not Necessary | 60.00 FL    | *- FL        |
| 38  | 1   |          | *REAR EXHAUST PIPE              | Repair        | 689.00 FL   | *- FL        |
| 39  | 1   |          | *REAR EXHAUST MOUNTING          | Not Necessary | 65.00 FL    | *- FL        |
| 40  | 1   |          | *REAR EXHAUST BRACKET           | Not Necessary | 121.00 FL   | *- FL        |
| 41  | 1   |          | *REAR NUMBER PLATE              | Not Necessary | 50.00 FS    | *- FS        |
| 42  | 1   |          | *REAR BUMPER CLIP               | Necessary     | 60.00 FS    | *30.00 FS    |
| 43  | 1   |          | *TAILGATE SEALANT               | Not Necessary | 80.00 FS    | *- FS        |
| 44  | 1   |          | *TAILGATE COMPANY STICKER       | Necessary     | 500.00 FS   | *100.00 FS   |
| 45  | 1   |          | *TAILGATE STICKER (70KM/H)      | Necessary     | 50.00 FS    | *30.00 FS    |
| 46  | 1   |          | *TAILGATE STICKER (5 PAX)       | Necessary     | 50.00 FS    | *10.00 FS    |
| 47  | 1   |          | *TAILGATE OUTER GARNISH CLIP    | Not Necessary | 50.00 FS    | *- FS        |
| 48  | 1   |          | *TAILGATE INNER BOARD CLIP LH   | Not Necessary | 40.00 FS    | *- FS        |
| 49  | 2   |          | *TAILGATE WINDSCREEN SEALANT    | Necessary     | 160.00 FS   | *100.00 FS   |
| 50  | 2   |          | *TAILGATE WINDSCREEN INNER SEAL | Not Necessary | 160.00 FS   | *- FS        |
| 51  | 1   |          | *TAIL LAMP CLIP                 | Not Necessary | 30.00 FS    | *- FS        |
| 52  | 1   |          | *REAR FLOOR PANEL MAT           | Not Necessary | 800.00 FS   | *- FS        |
| 53  | 1   |          | *REAR FLOOR PANEL TOP BOARD     | Not Necessary | 800.00 FS   | *- FS        |
| 54  | 1   |          | *REAR END PANEL (INNER) SEALANT | Not Necessary | 150.00 FS   | *- FS        |
| 55  | 1   |          | *REAR END PANEL (OUTER) SEALANT | Not Necessary | 150.00 FS   | *- FS        |

Report was unsubmitted during this print-out.

| No.                                          | Qty | Part No. | Particulars               | Condition                                           | Repairer's | Amount     |
|----------------------------------------------|-----|----------|---------------------------|-----------------------------------------------------|------------|------------|
| 56                                           | 1   |          | *REVERSE SENSOR           | Not Working                                         | 380.00 FS  | *200.00 FS |
| 57                                           | 1   |          | *REVERSE CAMERA           | Not Necessary                                       | 650.00 FS  | *- FS      |
| 58                                           | 1   |          | *REAR FLOOR PANEL SEALANT | Not Necessary                                       | 80.00 FS   | *- FS      |
| F=Franchise part. S=SpcNett. L=ListItemDisc. |     |          |                           |                                                     |            |            |
|                                              |     |          |                           | Sub Total (\$\$)                                    | 18,999.20  | 4,158.40   |
|                                              |     |          |                           | - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,475.92   | 368.84     |
|                                              |     |          |                           | Total Parts (\$\$)                                  | 17,523.28  | 3,789.56   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                     | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                 |          |                 |                 |
| 1                               | PANEL BEATING ,REMOVAL AND REPLACING PARTS      | New      | 1,800.00        | 500.00          |
| 2                               | TO SPRAY PAINT AFFECTED AREA                    | New      | 1,600.00        | 500.00          |
| 3                               | TRANSFER BOTH TAILGATE MECHAISM                 | New      | 300.00          | 100.00          |
| 4                               | CONDUCT WATER LEAKAGE TEST                      | New      | 100.00          | 30.00           |
| 5                               | REMOVE AND REFIT REAR RACK TO FACILITATE REPAIR | New      | 300.00          | 0.00            |
| 6                               | REAR CHASSIS ALIGHMENT                          | New      | 300.00          | 0.00            |
| 7                               | REMOVE AND REFIX REAR REVERSE SENSOR            | New      | 150.00          | 30.00           |
| 8                               | REMOVE AND REFIX REAR REVERSE CAMERA            | New      | 180.00          | 0.00            |
| 9                               | REMOVE AND INSTALL CARPET ,TRIM AND INTERIOR    | New      | 400.00          | 0.00            |
| 10                              | WIRING ,BULB CHECKING                           | New      | 50.00           | 0.00            |
| 11                              | RMEOVE AND REFIX BOTH TAILGATE WINDSCREEN       | New      | 300.00          | 120.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                 |          | <b>5,480.00</b> | <b>1,280.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >