

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013279/GVY3N2**Date:** 10/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00121812007

Claimant Vehicle No : GBF9488L **Insured Vehicle No :** GY984X

Date of Loss: 24/12/2021 Nature of Claim: TP Claim No: SNM21D207551/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9488L**

Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M) Engine No: R9MA503C016238

Reg. Date: 02/05/2017 (Man. Year: 2017) Chassis No: WDF44760323270849

Colour: White Odometer: 113694 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R16 Rear Tyre Size: 205/65R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,092.00	2,910.00	182.00	5.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	630.00	1,350.00	68.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,072.00	3,540.00	1,532.00	30.21
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	5,072.00	2,800.00	2,272.00	44.79
+ GST 7.00/7.00% (\$\$)	355.04	196.00	159.04	44.79
Nett Amount (\$\$)	5,427.04	2,996.00	2,431.04	44.79

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 03/01/2022 Inspected At: CARZ AUTO SERVICES PTE LTD
NO 61, WOODLANDS INDUSTRIAL PARK E9,
#04-04 E9 PREMIUM
SINGAPORE 757047

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Mar 2022)	
Parts:	N/A	MERCEDES-BENZ VITO 109 1.6 CDI LONG (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9488L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Damaged	1,100.00 FL	*1,100.00 FL
2	1		*FRONT BUMPER MOUNT PLATE LH	Not Necessary	100.00 FL	*- FL
3	1		*FRONT BUMPER INNER SUPPORT LH	Not Necessary	80.00 FL	*- FL
4	1		*FRONT HEADLAMP LH	Scratched	2,100.00 FL	*2,100.00 FL
5	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					3,430.00	3,230.00
- List Item Discount on L Items 10.00/10.00% (S\$)					338.00	320.00
Total Parts (S\$)					3,092.00	2,910.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW FRONT DAMAGED PARTS,REPLACE REALIGNED ALL AFFECTED PARTS	New	800.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	200.00
3	TO REMOVE/REFIX WIRING CHECKS	New	60.00	30.00
4	TO TUFFCOAT AFFECTED AREA	New	120.00	0.00
Gross Labour Cost (\$\$)			1,980.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >