



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205833

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/09/2022
Reference CC6/CTI21013280/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YP 6780L
Insured Veh. GBH 3047E
Claim No. SNM21D207679/C02
Policy No. DMCVSNW00033052101
Accident Date 28/12/2021
Inspection Date 30/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21013280/Aea3q2 Date: 20/09/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 3047E	Veh. Inspected	YP 6780L	
Policy No.	DMCVSNW00033052101	Coverage (\$)	0.00	
Claim No.	SNM21D207679/C02	Excess (\$)	0.00	
Assign From		Assign Date	30/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NHR85	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JAANHR85EH7100206	Colour	WHITE	
Odometer	174367 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	185 R14C	MICHELIN	6 mm	
L/H Rear Tyre	185 R14C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2021	Inspection Date	30/12/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6780L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT O/S HEAD LAMP	CRACKED	810.00	585.00
1	FRONT O/S SIGNAL LAMP	CRACKED	546.60	260.00
1	FRONT O/S WING MIRROR (SQUARE)	N/S	268.10	-
1	FRONT O/S WING MIRROR BRACKET	BENT	506.70	285.00
1	FRONT O/S WING MIRROR BRACKET GARNISH	NOT NECESSARY	96.70	-
1	FRONT O/S DOOR PILLAR GARNISH	CRACKED	696.20	351.00
1	FRONT O/S DOOR	DENTED	2,286.20	1,120.00
2	FRONT O/S DOOR HINGES	NOT NECESSARY	200.00	-
1	FRONT O/S DOOR SEAL (FRONT PORTION)	NOT NECESSARY	135.60	-
1	FRONT O/S DOOR STICKER	NECESSARY	322.40	120.00
1	FRONT O/S DOOR WEATHERSTRIP	NOT NECESSARY	506.20	-
1	FRONT O/S DOOR SIGNAL LAMP	CUT	120.00	120.00
	LESS 15% DISCOUNT		-974.21	-426.15
			5,520.49	2,414.85
	<u>SPECIAL NETT ITEMS</u>			
2	FRONT O/S HEAD LAMP CLIPS (SN)	NECESSARY	24.00	10.00
2	FRONT O/S SIGNAL LAMP CLIPS (SN)	NECESSARY	24.00	10.00
6	FRONT O/S DOOR PILLAR GARNISH CLIPS (SN)	NECESSARY	72.00	20.00
			120.00	40.00
	<u>LABOUR</u>			
	TO DISMANTLE ,STRAIGHTEN & WELDING.		800.00	500.00
	TO SPRAY PAINTING.		800.00	400.00
	TO REMOVE AND REPLACE FRONT O/S DOOR FITTINGS.		140.00	60.00
	TO CHECK WIRING.		120.00	30.00
	TO RE-SEAL ANTI RUST.		80.00	40.00
			1,940.00	1,030.00
	GRAND TOTAL		7,580.49	3,484.85



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	----------

Report Ref No. CC6/CTI21013280/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 6780L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

