

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21013281/KEA3Q2**Date:** 30/03/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHD482B**Insured Vehicle No :** SMV842S

Date of Loss: 24/12/2021

Nature of Claim: TP

Claim No: 5311219581SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD482B**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C003223

Reg. Date: 07/08/2017 (Man. Year: 2016)

Chassis No: VF1ABL15AUC283292

Colour: Metallic White/Red

Odometer: 292579 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,114.28	393.39	2,720.89	87.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	785.00	6,795.00	89.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,694.28	1,178.39	9,515.89	88.98
Approved Total (Overridden) (S\$)		950.00		
(S\$)	10,694.28	950.00	9,744.28	91.12
+ GST 7.00/7.00% (S\$)	748.60	66.50	682.10	91.12
Nett Amount (S\$)	11,442.88	1,016.50	10,426.38	91.12
+ Loss of Use (5.5 x S\$50.00/day) (S\$)		275.00		
+ Car Rental (5.5 x S\$81.13/day) (S\$)		446.22		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,745.17		
Global Sum Settlement (S\$)		1,740.00		

INSPECTION

Date of Assignment: 27/12/2021

Date Inspected: 27/12/2021 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	747.20 FL	*- FL
2	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
3	1		*HEADLAMP LH	Serviceable	743.60 FL	*- FL
4	1		*HEADLAMP PANEL FRT LH	Repair	128.30 FL	*- FL
5	1		*FENDER PANEL FRT LH	Bent	437.10 FL	*437.10 FL
6	1		*WHEELARCH FRT LH	Serviceable	191.40 FL	*- FL
7	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
8	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
9	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
10	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
11	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
12	1		*BUMPER CLIP FRT	Not Necessary	85.00 FS	*- FS
13	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,440.31	437.10
- List Item Discount on L Items 10.00/10.00% (\$)	326.03	43.71
Total Parts (\$)	3,114.28	393.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	300.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	440.00
3	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
Gross Labour Cost (\$)			7,580.00	785.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >