

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013282/RQY3N2**Date:** 03/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00094112103

Claimant Vehicle No : SJJ1365U **Insured Vehicle No :** XE4269E

Date of Loss: 24/12/2021 Nature of Claim: TP Claim No: SNM21D207586/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ1365U**

Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZC986524

Reg. Date: 02/09/2008 (Man. Year: 2008) Chassis No: NZT2603022134

Colour: Grey Odometer: 157758 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,459.35	1,986.85	472.50	19.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,200.00	1,120.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,779.35	3,186.85	1,592.50	33.32
Approved Total (Overridden) (\$\$)		2,550.00		
(\$\$)	4,779.35	2,550.00	2,229.35	46.65
+ GST 7.00/7.00% (\$\$)	334.55	178.50	156.05	46.64
Nett Amount (\$\$)	5,113.90	2,728.50	2,385.40	46.65

INSPECTION

Date of Assignment: 07/01/2022

Date Inspected: 29/12/2021 Inspected At: Mova Automotive Pte Ltd (FAN YOONG BRANCH)
15 Fan Yoong Road, CNG Singapore Centre
Singapore 629792

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2022)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ1365U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	168.00 FL	*168.00 FL
2	1		*REAR FENDER RH	Buckled	1,350.00 FL	*1,100.00 FL
3	1		*REAR FENDER INNER TRIM RH	Deformed	385.00 FL	*385.00 FL
4	1		*REAR FENDER COWLING RH	Not Necessary	55.00 FL	*- FL
5	1		*REAR FENDER AIR DUCT RH	Not Necessary	135.00 FL	*- FL
6	1		*TAILLAMP ASSY RH	Cracked	315.00 FL	*315.00 FL
7	1		*TAILLAMP PANEL RH	Not Necessary	115.00 FL	*- FL
8	2		*TAILLAMP CLIPS	Necessary	17.80 FL	*17.80 FL
9	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR BUMPER	Deformed	555.00 FL	*555.00 FL
11	1		*REAR BUMPER RETAINER RH	Not Necessary	75.00 FL	*- FL
12	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
13	1		*REAR SHOCK ABSORBER RH (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,265.80	2,635.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	806.45	648.95
Total Parts (\$\$)	2,459.35	1,986.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD REAR FENDER RH,TAILLAMP PANEL RH.REMOVE & REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION	New	1,000.00	600.00
2	SPRAY PAINT REAR FENDER RH,TAILLAMP PANEL RH,REAR END PANEL,REAR FENDER INNER PANEL RH.REAR BUMPER	New	800.00	400.00
3	REMOVE & REPLACE REAR WINDSCREEN & CHECK WATER LEAKAGE	New	120.00	120.00
4	REMOVE & REPLACE REAR SPEAKER BOARD,REAR SEAT ASSY,REAR FLOOR CARPET,UPHOLSTERY	New	160.00	80.00
5	REMOVE & REPLACE REAR UNDER CARRIAGE SUSPENSION	New	180.00	0.00
6	COMPUTER WHEEL ALIGNMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			2,320.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >