

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013283/KPA3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070016239
Claimant Vehicle No :	GBC9119T	Insured Vehicle No :	GZ5550B
Date of Loss:	28/12/2021	Nature of Claim:	TP
		Claim No:	0392634780SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC9119T	Engine No:	1KD2860557
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y20K213751
Reg. Date:	26/07/2019 (Man. Year: 2019)	Odometer:	96900 km
Colour:	Yellow		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Michelin 2 mm	Rear Left Side:	Falken 9/9 mm
Front Right Side:	Michelin 2 mm	Rear Right Side:	Falken 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,650.15	10,007.55	642.60	6.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,740.00	5,580.00	1,160.00	17.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,390.15	15,587.55	1,802.60	10.37
+ GST 7.00/7.00% (\$\$)	1,217.31	1,091.13	126.18	10.37
Nett Amount (\$\$)	18,607.46	16,678.68	1,928.78	10.37
+ Car Rental (15.0 x S\$105.00/day) (\$\$)		1,575.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		18,255.68		

INSPECTION

Date of Assignment:	29/12/2021	
Date Inspected:	31/12/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	11.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	718.90 FL	*718.90 FL
2	1		*FRONT BUMPER BRACKETS	O/S Bent	599.00 FL	*299.50 FL
3	1		*FRONT GRILLE	Cracked	577.50 FL	*577.50 FL
4	1		*FRONT GRILLE LOGO	Necessary	71.00 FL	*71.00 FL
5	6		*FRONT GRILLE CLIPS	Necessary	21.00 FL	*21.00 FL
6	1		*RH HEADLAMP	Cracked	1,078.70 FL	*1,078.70 FL
7	1		*FRONT PANEL	Bent	1,094.30 FL	*1,094.30 FL
8	1		*FRONT PANEL EMBLEM (DYNA)	Necessary	67.00 FL	*67.00 FL
9	1		*FRONT WIPER PANEL	Bent	311.80 FL	*311.80 FL
10	1		*FRONT WIPER LINKAGE	Serviceable	318.90 FL	*- FL
11	1		*FRONT RH DOOR REAR PILLAR EMBLEM (D4D)	Necessary	49.60 FL	*49.60 FL
12	1		*AIRCON EVAPORATOR	Housing Cracked	2,674.00 FL	*2,674.00 FL
13	1		*RH TAILLAMP	Cracked	222.10 FL	*222.10 FL
14	1		*TAILLAMP PANELS	O/S Bent	132.40 FL	*66.20 FL
15	1		*REAR NUMBER PLATE GARNISH	Serviceable	172.20 FL	*- FL
16	1		*REAR NUMBER PLATE	Bent	20.00 FS	*20.00 FS
17	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
18	1		*FRONT NUMBER PLATE	Bent	20.00 FS	*20.00 FS
19	1		*RH TAILGATE WITH INNER STAINLESS STEEL PROTECTOR	Bent	1,450.00 FS	*1,450.00 FS
20	1		*RH TAILGATE BOTTOM HINGE	Bent	180.00 FS	*180.00 FS
21	1		*RH TAILGATE TOP HINGE	Distorted	180.00 FS	*180.00 FS
22	1		*RH TAILGATE OPENER	Bent	390.00 FS	*390.00 FS
23	1		*LH TAILGATE WITH INNER STAINLESS STEEL PROTECTOR	Bent	1,450.00 FS	*1,450.00 FS
24	1		*STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
25	1		*DASHBOARD LH LOWER GARNISH	Mtg Cracked	304.20 FL	*304.20 FL
26	1		*DASHBOARD LH LOWER GARNISH INNER	Cracked	298.10 FL	*298.10 FL
27	1		*FRONT RH DOOR INNER LOCK	Dented	289.50 FL	*289.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,900.20	12,043.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,250.05	2,035.85
Total Parts (\$\$)	10,650.15	10,007.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	60.00	60.00
2	REMOVE AND REFIX AIRCON CHECK VACUUM & REFILL GAS	New	100.00	100.00
3	REMOVE & REFIX DASHBOARD METER ASSY AND CHECK WIRING	New	280.00	250.00
4	REMOVE & REFIX FRT BUMPER ASSY ,HEADLAMPS, GRILLE ,FRT WIPER PANEL & WIPER ASSY ,CUT ,WELD & RENEW FRT PANEL ,STRAIGHTEN ,KNOCK & REPAIR FRT RH W/SCREEN PILLAR ,CABIN REAR RH PILLAR ,REPAIR ,REALIGN CABIN FRT CROSS BAR & REALIGN CABIN POSITION	New	1,000.00	800.00
5	REMOVE & REFIX NUMBER PLATE BRACKET ,TAILLAMP & BRACKETS ,STRAIGHTEN ,KNOCK & REPAIR REAR TRUCK END MEMBER ,FLOOR BOARD AND REALIGN THE SAME	New	800.00	700.00
6	PUTTY & RESPRAY ON FRT PANEL ,WIPER PANEL ,FRT GRILLE ,FRT BUMPER ,FRT RH DOOR REAR PILLAR AND FRT AFFECTED AREAS	New	800.00	720.00
7	PUTTY & RESPRAY REAR TRUCK END CROSS MEMBER AND FLOOR BOARD	New	500.00	500.00
8	REMOVE & REFIX TAILGATE REPLACE TAILGATE INNER STAINLESS STEEL ,REMOVE & REFIX REAR DAMAGE STAINLESS STEEL DECKING AND CANOPY & CHECK LEAKING	New	2,000.00	1,500.00
9	TO REWRITE ADVERTISEMENT	New	1,000.00	750.00
10	TO SUPPLY IUNIT WIRE SOCKET REPAIR WIRE HARNESS AND CHECK WIRING	New	200.00	200.00
Gross Labour Cost (\$\$)			6,740.00	5,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >