

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	-		R	ef:	CS/TP21013288/R1vce2
	LI XIAOWEN 14 CLIFTON VALE SINGAPORE 3596		Da	ate:	12/04/2022
			C	ode:	TP2
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.		Veh. Inspected		SLB 1510K
	Policy No.		Coverage (\$)		0.00
	Claim No.	Excess (\$)		0.00	
	Assign From		Assign Date		29/12/2021
2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT 3008 1.2 EAT8 ACTIVE P	c.c		1199
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	VF3MRHNSUMS131835	Colour		BLUE
	Odometer	7671 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/65 R17	MICHELIN		6 mm
	L/H Front Tyre	215/65 R17	MICHELIN		6 mm
	R/H Rear Tyre	215/65 R17	MICHELIN		6 mm
	L/H Rear Tyre	215/65 R17	MICHELIN		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/11/2021	Inspection Date		29/12/2021
	Survey held at	AUTOFRANCE			
		305, ALEXANDRA ROAD SINGAPORE 159942.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 13 Working Days				