

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013290/RVY3N2**Date:** 15/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00145162100
Claimant Vehicle No :	YP5660G	Insured Vehicle No :	GBF5152G
Date of Loss:	20/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207418/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP5660G		
Make & Model:	MITSUBISHI FUSO, 3.0 D FM65FM2RDEB (M)	Engine No:	6M60221209
Reg. Date:	01/03/2017 (Man. Year: 2016)	Chassis No:	FM65FMA30175
Colour:	White	Odometer:	254578 km
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	11R22.5	Rear Tyre Size:	11R22.5(D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,195.00	2,117.00	8,078.00	79.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	2,900.00	3,700.00	56.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,795.00	5,017.00	11,778.00	70.13
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	16,795.00	4,000.00	12,795.00	76.18
+ GST 7.00/7.00% (\$\$)	1,175.65	280.00	895.65	76.18
Nett Amount (\$\$)	17,970.65	4,280.00	13,690.65	76.18

INSPECTION

Date of Assignment:	11/01/2022	
Date Inspected:	30/12/2021	Inspected At: JIT Keong Trading Co. Pte Ltd (HQ) 28 Benoi Place Singapore 629945
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Mar 2022)	
Parts:	N/A	mitsubishi fuso 3.0 d fm65fm2rdeb (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP5660G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNIT SIDE GUARD R/H	Broken	1,900.00 F	*1,200.00 FL
2	1		*SIDE GUARD SUPPORT (3 Set)	Bent (1 Set only)	360.00 F	*120.00 FL
3	1		*UNIT TOOLS BOX	Bent	750.00 F	*550.00 FL
4	1		*UNIT REAR ALUMINIUM MUDGUARD	Cracked	700.00 F	*500.00 FL
5	1		*SET TOOLS BOX BRACKET	Not Necessary	160.00 F	*- FL
6	1		*REAR MUDFLAP	Not Necessary	40.00 F	*- FL
7	1		*SET HOOKLIFT DULL CHASSIS	Repair	5,800.00 F	*- FL
8	1		*TYRE REAR RH OUTER (70%)	Cut	485.00 FS	*339.50 FS
					Sub Total (S\$)	10,195.00 2,709.50
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 592.50
					Total Parts (S\$)	10,195.00 2,117.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGE,REFIX PARTS,CIT & WELD & ALIGN TO POSITION	New	4,500.00	2,300.00
2	CRANE SERVICE TO LIFT HOOKLIFT IN ORDER TO FACILATE REPAIR	New	800.00	0.00
3	M.E TESTING/CERTIFY	New	400.00	0.00
4	SPRAY PAINTING TO AFFECTED AREA	New	900.00	600.00
Gross Labour Cost (\$\$)			6,600.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >