

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013292/AVY3N2**Date:** 10/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00025962100

Claimant Vehicle No : GBD2388Z **Insured Vehicle No :** GBE9779C

Date of Loss: 27/12/2021 Nature of Claim: TP Claim No: SNM21D207629/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD2388Z**

Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D053695

Reg. Date: 01/08/2014 (Man. Year: 2014) Chassis No: VSKYBAM20Z0087195

Colour: Silver Odometer: 126507 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14

Front Left Side: Linglong 6 mm Rear Left Side: Linglong 6 mm

Front Right Side: Linglong 6 mm Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,220.00	3,562.45	1,657.55	31.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	860.00	320.00	27.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,400.00	4,422.45	1,977.55	30.90
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	6,400.00	3,500.00	2,900.00	45.31

INSPECTION

Date of Assignment: 09/06/2022

Date Inspected: 29/12/2021 Inspected At: Tk Motor (HQ)
BLK 1 KAKI BUKIT AVE 6 #02-56 AUTOBAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Jun 2022)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD2388Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	864.00 F	*864.00 FL
2	2		*FRONT BONNET HINGE	Not Necessary	178.00 F	*- FL
3	7		*FRONT BONNET INSULATOR CLIP	Not Necessary	28.00 F	*- FL
4	2		*FRONT HEADLAMP	Cracked	1,158.40 F	*1,158.40 FL
5	1		*FRONT GRILLE	Cracked	503.60 F	*368.00 FL
6	6		*FRONT GRILLE CLIP	Necessary	24.00 F	*24.00 FL
7	1		*FRONT GRILLE EMBLEM	Necessary	131.70 F	*131.70 FL
8	1		*FRONT GRILLE GARNISH	Cracked	79.40 F	*79.40 FL
9	1		*FRONT SUPPORT TOP PANEL	Repair	327.90 F	*- FL
10	1		*FRONT SUPPORT PANEL L/H SIDE GARNISH	Not Necessary	48.40 F	*- FL
11	3		*FRONT SUPPORT PANEL L/H SIDE GARNISH CLIP	Not Necessary	12.00 F	*- FL
12	1		*FRONT BUMPER	Deformed	610.30 F	*610.30 FL
13	1		*FRONT BUMPER CLIP (16 Pcs)	Necessary	64.00 F	*30.00 FL
14	2		*FRONT BUMPER RIGHT AND LEFT TOP GARNISH	Deformed	513.40 F	*513.40 FL
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	503.60 F	*- FL
16	1		*FRONT BUMPER SPONGE	Cracked	121.30 F	*121.30 FL
17	1		*FRONT NO PLATE	Dented	26.00 FS	*26.00 FS
18	1		*FRONT NO PLATE COVER	Deformed	26.00 FS	*26.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,220.00	3,952.50
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	390.05
Total Parts (S\$)	5,220.00	3,562.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO TOP-UP AIR-CON GAS	New	100.00	0.00
3	TO SPRAY PAINTING	New	400.00	400.00
4	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	30.00
5	TO PANEL BEATING AND WELDING,REMOVING ALL DAMAGE PARTS & REPLACING OF THE NEW PARTS ETC	New	550.00	400.00
Gross Labour Cost (\$\$)			1,180.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >