

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013293/BPA3Q2**Date:** 13/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMS5947G	Insured Vehicle No :	SLN470K
Date of Loss:	21/12/2021	Nature of Claim:	TP Claim No: 8250967777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5947G	Engine No:	LEB6744339
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU31324338
Reg. Date:	03/03/2020 (Man. Year: 2018)	Odometer:	51038 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,481.36	3,100.00	9,381.36	75.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	1,850.00	2,800.00	60.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,131.36	4,950.00	12,181.36	71.11
+ GST 7.00/7.00% (S\$)	1,199.20	346.50	852.70	71.11
Nett Amount (S\$)	18,330.56	5,296.50	13,034.06	71.11
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,587.95		
Global Sum Settlement (S\$)		6,500.00		

INSPECTION

Date of Assignment:	29/12/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	30/12/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	10.0 days	

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,436.20 FL	*953.00 FL
2	1		*TAILGATE OUTER GARNISH	Not Damaged	285.00 FL	*- FL
3	1		*TAILGATE LOGO	Necessary	95.80 FL	*45.00 FL
4	1		*TAILGATE EMBLEM VEZEL	Necessary	89.40 FL	*66.80 FL
5	1		*TAILGATE EMBLEM HYBRID	Necessary	78.30 FL	*45.00 FL
6	2		*TAILGATE LAMP	Not Damaged	1,092.00 FL	*- FL
7	1		*TAILGATE INNER LOCK	Jammed	156.70 FL	*156.70 FL
8	1		*TAILGATE INNER TRIMBOARD	Not Damaged	386.20 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Torn	198.40 FL	*162.30 FL
10	1		*REAR WINDSCREEN MOULDING SIDE	Necessary	88.60 FL	*88.60 FL
11	1		*REAR WINDSCREEN MOULDING TOP	Necessary	108.00 FL	*108.00 FL
12	1		*REAR WINDSCREEN MOULDING BOTTOM	Necessary	108.00 FL	*108.00 FL
13	1		*REAR BUMPER	Dented	989.50 FL	*762.70 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	170.00 FL	*136.60 FL
15	1		*REAR BUMPER BRACKET	No such part	135.60 FL	*- FL
16	2		*REAR BUMPER REFLECTOR	Not Damaged	256.00 FL	*- FL
17	2		*REAR BUMPER SIDE GARNISH	Not Damaged	477.80 FL	*- FL
18	1		*REAR END PANEL	Dented	695.80 FL	*517.30 FL
19	1		*REAR END PANEL TOP GARNISH	Not Damaged	184.00 FL	*- FL
20	2		*REAR SIDE END PANEL	Not Damaged	1,084.60 FL	*- FL
21	2		*TAILLAMP	Not Damaged	1,316.60 FL	*- FL
22	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,312.40 FL	*- FL
23	1		*SMART BUZZER	Broken	195.00 FL	*150.00 FL
24	2		*REAR FENDER ARCH GARNISH	Not Damaged	436.60 FL	*- FL
25	1		*SPARE TYRE PANEL LOWER SPLASH COVER	Not Damaged	316.00 FL	*- FL
26	1		*REAR EXHAUST	Not Damaged	896.20 FL	*- FL
27	1		*REAR EXHAUST MOUNTING	Not Damaged	88.00 FL	*- FL
28	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
29	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
30	1		*TAILGATE LAMP CLIPS	No such part	60.00 FS	*- FS
31	1		*TAILGATE LAMP SEAL	Not Necessary	60.00 FS	*- FS
32	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*TAILGATE TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*TAILGATE WINDSCREEN CLIPS	No such part	50.00 FS	*- FS
35	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
37	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	100.00 FS	*- FS
38	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
40	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
41	1		*REAR SIDE END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
42	1		*TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
44	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
45	1		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*REVERSE CAMERA	Not Damaged	450.00 FS	*- FS
47	2		*REVERSE SENSOR WITH MODULE	Scratched	500.00 FS	*200.00 FS
48	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,016.70	3,760.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,535.34	660.00
Total Parts (\$)	12,481.36	3,100.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R REVERSE SENSOR	New	150.00	50.00
3	R&R REAR WINDSCREEN	New	300.00	120.00
4	R&R REAR EXHAUST	New	150.00	0.00
5	R&R UPHOLSTERY	New	300.00	0.00
6	CHECK WIRING	New	120.00	0.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
8	PANEL BEAT	New	1,600.00	1,000.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$\$)			4,650.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >