LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21013295/R1QF3E2

06/01/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SJX8935E Insured Vehicle No: SMS7061Z

No:

Date of Loss: 23/12/2021 Nature of Claim: TP Claim No: 6743911707SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX8935E

MITSUBISHI LANCER, 1.5 MIVEC SPORTS AT ABS Make & Model:

Engine No: 4A910170866 D/AB (A)

21/07/2010 (Man. Year: 2010) JMYSRCY2AAU001852 Reg. Date: Chassis No:

Colour: White Odometer: 137636 km

Engine Capacity: 1499 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Rear Right Side: Front Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/12/2021

Ah Koon Motor (1960) Pte Ltd (HQ) Date Inspected: 30/12/2021 Inspected At:

BLK 1001 BUKIT MERAH LANE 3, #01-69

Singapore 159718

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$34,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT LH DOOR	Repair	0.00 F	*-F
2	1	*FRT LH DOOR WING MIRROR COVER	Missing	0.00 F	*- F
3	1	*FRT LH DOOR OUTER HANDLE	Repair	0.00 F	*- F
4	1	*ROCKER PANEL LH	Repair	0.00 F	*- F
5	1	*FRT BUMPER	Scratched	0.00 F	*- F
6	1	*FRT BUMPER FOG LAMP COVER	Scratched	0.00 F	*- F
7	1	*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
8	1	*FRT LH HEADLAMP ASSY	Scratched	0.00 F	*- F
9	1	*FRT LH FENDER	Bent	0.00 F	*- F
10	1	*FRT LH FENDER PROTECTOR	Deformed	0.00 F	*- F
11	1	*BONNET	Repair	0.00 F	*- F
12	1	*FRT LH WHEEL RIM	Scratched	0.00 F	*- F
13	1	*FRT LH WHEEL TYRE	Scratched	0.00 F	*- F
14	1	*REAR LH DOOR	Repair	0.00 F	*- F
15	1	*REAR BUMPER	Repair	0.00 F	*- F
16	1	*REAR LH FENDER	Repair	0.00 F	*-F
F=Fr	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >