



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 3333R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR (CONSISTENT)	DENTED	1,863.00	1,863.00
1	FRONT RH DOOR LOCK (CONSISTENT)	NOT NECESSARY	249.00	-
1	FRONT RH DOOR WEATHERSTRIPE (CONSISTENT)	NECESSARY	347.00	347.00
1	FRONT RH WING MIRROR (CONSISTENT)	TO REPAIR SEE LABOUR	1,623.00	-
1	REAR RH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,942.00	-
1	REAR RH DOOR LOCK (CONSISTENT)	NOT NECESSARY	254.00	-
1	REAR RH DOOR WEATHERSTIPE (CONSISTENT)	NOT NECESSARY	241.00	-
1	REAR RH DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY	149.00	-
1	SILL PANEL OUTER GARNISH (CONSISTENT)	TO REPAIR SEE LABOUR	695.00	-
	LESS 10% DISCOUNT		-	-221.00
			7,363.00	1,989.00
	<u>SPECIAL NETT ITEMS</u>			
1	SILL PANEL OUTER GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT RH WING MIRROR, REAR RH DOOR AND SILL PANEL OUTER GARNISH.		800.00	500.00
	SPRAY PAINTING.		1,000.00	800.00
	WIRING.		100.00	30.00
	TO TRANSFER FRONT AND REAR DOOR FITTINGS.		300.00	80.00
			2,200.00	1,410.00
GRAND TOTAL			9,613.00	3,399.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/ASM21013296/Aty3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.