

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21013297/T1ty3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 11/01/2022 SINGAPORE 068811 ATTN: OH VALE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 2785U FBL 4934S Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03O2T Excess (\$) 0.00 **OH VALE Assign Date** 29/12/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA FZN150 c.c 149 Make & Model HIDDEN 2016 Engine No. Year of Reg. ME1RG1619G2002001 RED Chassis No. Colour Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 110/70 R17 PIRELLI 5 mm L/H Front Tyre mm 130/70 R17 **PIRELLI** R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. 5. **General Information** 10/12/2021 Inspect Date / Time 03/01/2022 (11:30 AM) Accident Date **EQUATOR BROTHERHOOD** Survey held at 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM21013297/T1ty3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

5 Working Days

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor