

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21013301/UTY3N2**Date:** 03/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00128872104

**Claimant Vehicle No :** GBH8141H **Insured Vehicle No :** YP4833G

Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: SNM21D207611/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBH8141H**

Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KD2826482

Reg. Date: 28/09/2018 (Man. Year: 2018) Chassis No: JTFHT02P200245152

Colour: White Odometer: 157288 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15 Rear Tyre Size: 195R15

Front Left Side: CST 6 mm Rear Left Side: CST 6 mm

Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,205.64	1,482.56	723.08	32.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	560.00	670.00	54.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,435.64</b>	<b>2,042.56</b>	<b>1,393.08</b>	<b>40.55</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	3,435.64	1,600.00	1,835.64	53.43
<b>+ GST 7.00/7.00% (S\$)</b>	240.49	112.00	128.49	53.43
<b>Nett Amount (S\$)</b>	<b>3,676.13</b>	<b>1,712.00</b>	<b>1,964.13</b>	<b>53.43</b>

**INSPECTION**

Date of Assignment: 24/02/2022

Date Inspected: 25/01/2022 Inspected At: Precise Auto Services (HQ)  
NO.1 KAKI BUKIT AVE 6 #02-34/36  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Mar 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH8141H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Badly Dented	1,318.10 FL	*1,318.10 FL
2	2		*FRONT DOOR HINDGE-RH (TOP & BOTTOM)	Bent/Twisted	344.20 FL	*344.20 FL
3	1		*FRONT DOOR WEATHER STRIPE-RH	Not Necessary	195.20 FL	*- FL
4	2		*FRONT DOOR INNER LOCK-RH	Not Necessary	748.90 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE-RH	Cracked	274.45 FL	*274.45 FL
6	1		*FRT R.O.C STICKER O/S	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,925.85</b>	<b>1,966.75</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	720.21	484.19
<b>Total Parts (\$\$)</b>	<b>2,205.64</b>	<b>1,482.56</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX FRONT RH DOOR MECHANISM	New	280.00	60.00
2	TO RESPRAY AFFECTED AREAS	New	450.00	300.00
3	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR FRONT RH DOOR PILLAR & ALIGNED ALL PARTS	New	500.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>1,230.00</b>	<b>560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >