

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013304/AQY3N2**Date:** 25/05/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00079312102
Claimant Vehicle No :	GBG296C	Insured Vehicle No :	GBC9119T
Date of Loss:	28/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207664/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG296C		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30016219N
Reg. Date:	24/05/2017 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0859377
Colour:	Gold	Odometer:	155538 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R13
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,400.86	5,542.19	7,858.67	58.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,920.00	3,320.00	2,600.00	43.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,320.86	8,862.19	10,458.67	54.13
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	19,320.86	6,900.00	12,420.86	64.29
+ GST 7.00/7.00% (S\$)	1,352.46	483.00	869.46	64.29
Nett Amount (S\$)	20,673.32	7,383.00	13,290.32	64.29

INSPECTION

Date of Assignment:	04/01/2022	
Date Inspected:	30/12/2021 Inspected At:	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB, SINGAPORE 417921
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG296C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE EGR TUBE	Dented	206.60 FL	*206.60 FL
2	1		*EXHAUST CONVERTER HEAT SHIELD (INNER)	Not Necessary	121.00 FL	*- FL
3	1		*EXHAUST CONVERTER HEAT SHIELD (OUTER)	Dented	121.00 FL	*121.00 FL
4	1		*EXHAUST PIPE HEAT SHIELD (TOP)	Not Necessary	197.00 FL	*- FL
5	1		*FRONT LH DOOR END PANEL	Dented	1,842.40 FL	*950.00 FL
6	5		*LH SIDE GATE HINGES	Not Necessary	216.50 FL	*- FL
7	1		*REAR LH TAILLAMP BRACKET	Bent	46.00 FL	*46.00 FL
8	1		*REAR NUMBER PLATE BRACKET	Bent	48.00 FL	*48.00 FL
9	1		*REAR NUMBER PLATE LAMP	Not Necessary	54.00 FL	*- FL
10	1		*REAR TAILGATE	Dented	1,459.60 FL	*1,459.60 FL
11	1		*REAR TAILGATE NISSAN STICKER	Necessary	153.90 FL	*153.90 FL
12	1		*REAR TAILGATE FLIP LOCK HANDLE L/R	N/s Bent	370.00 FL	*185.00 FL
13	3		*REAR TAILGATE HINGES	Not Necessary	216.00 FL	*- FL
14	1		*REAR TAILGATE LOWER PANEL	Dented	886.40 FL	*450.00 FL
15	2		*REAR TAILGATE LOWER RUBBER STOPPER L/R	Not Necessary	32.00 FL	*- FL
16	1		*REAR TAILLAMP L/R	N/s Cracked	430.00 FL	*215.00 FL
17	1		*SIDE GATE L/R	N/s Dented	5,821.00 FL	*1,860.00 FL
18	1		*ENGINE WATER PIPE TUBE	Dented	110.00 FS	*110.00 FS
19	1		*GEAR BOX MOUNTING	Torn	91.60 FS	*91.60 FS
20	1		*LH SIDE GATE ALUMINIUM CHECKER PLATE	Not Necessary	800.00 FS	*- FS
21	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
22	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
23	1		*REAR REVERSE SENSOR BRACKET	Not Necessary	80.00 FS	*- FS
24	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
25	1		*REAR TAILGATE ALUMINIUM CHECKER PLATE	Not Necessary	600.00 FS	*- FS
26	1		*REAR TAILGATE ALUMINIUM CHECKER PLATE REPAIR KIT - SET	Not Necessary	120.00 FS	*- FS
27	2		*SIDE GATE ALUMINIUM CHECKER PLATE REPAIR KIT L/R	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,623.00 6,111.70
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,222.14 569.51

Total Parts (\$\$) 13,400.86 5,542.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.	New	80.00	80.00
2	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	60.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,500.00	1,000.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,500.00	1,000.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	80.00
6	TO REPAIR AND STRAIGHTER CHASSIS MEMBER AND REALIGN BACK POSITION.	New	1,800.00	600.00
7	TO REMOVE AND REFIX DECK CARRIER IN ORDER REPAIR ACCIDENT AFFECTED AREA	New	800.00	500.00
Gross Labour Cost (\$\$)			5,920.00	3,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >