

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21013306/UQY3E2

Date: 14/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00002912100		
Claimant Vehicle No :	GBD5226M	Insured Vehicle No :	SNC4373R		
Date of Loss:	10/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207246/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD5226M	Engine No:	1KD2443501
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	KDY2318017178
Reg. Date:	26/11/2014 (Man. Year: 2014)	Odometer:	129115 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6/6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,895.00	1,140.00	755.00	39.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	344.84	210.44	134.40	38.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,239.84	1,350.44	889.40	39.71
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,239.84	1,100.00	1,139.84	50.89
+ GST 7.00/7.00% (S\$)	156.79	77.00	79.79	50.89
Nett Amount (S\$)	2,396.63	1,177.00	1,219.63	50.89

INSPECTION

Date of Assignment:	11/01/2022	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	23/12/2021	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jul 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD5226M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		1,895.00 F	*1,140.00 F
F=Franchise part.						
Total Parts (S\$)					1,895.00	1,140.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL PAINT	New	155.84	155.84
2	TOTAL LABOUR	New	189.00	54.60
Gross Labour Cost (S\$)			344.84	210.44

Report was unsubmitted during this print-out.

< END OF ESTIMATES >