

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21013309/GGA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993598
Claimant Vehicle No :	SHD6123Z	Insured Vehicle No :	SLZ137K
Date of Loss:	18/12/2021	Nature of Claim:	TP
		Claim No:	6231970698SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6123Z	Engine No:	2ZR2F29644
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU403089147
Reg. Date:	26/12/2019 (Man. Year: 2019)	Odometer:	198504 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,754.60	749.03	7,005.57	90.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	430.00	1,760.00	80.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,944.60	1,179.03	8,765.57	88.14
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$73.00/day) (S\$)		438.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,924.03		

INSPECTION

Date of Assignment:	23/12/2021	
Date Inspected:	23/12/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Deformed	485.60 F	*364.20 F
2	2		*PAD ,RR BUMPER ,RH & LH 3 (DISC 25%)	Necessary	22.00 F	*16.50 F
3	2		*PAD ,RR BUMPER ,RH & LH 2 (DISC 25%)	Necessary	8.00 F	*6.00 F
4	2		*PAD ,RR BUMPER ,RH & LH 1 (DISC 25%)	Necessary	8.00 F	*6.00 F
5	3		*PAD ,RR BUMPER CTR (DISC 25%)	Necessary	33.00 F	*24.75 F
6	1		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	22.60 F	*16.95 F
7	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
8	1		*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Cut	374.50 F	*280.88 F
9	1		*REAR BUMPER REINFORCEMENT	Not Necessary	332.70 F	*- F
10	1		*RETAINER ,RR BUMPER RH	Not Necessary	132.60 F	*- F
11	1		*COVER ,GUARD RR BUMPER LOWER	Not Necessary	22.00 F	*- F
12	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,RH	Not Necessary	39.00 F	*- F
13	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,LH	Not Necessary	39.00 F	*- F
14	1		*COVER ,REAR FLOOR UNDER ,RH	Not Necessary	175.10 F	*- F
15	1		*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	241.90 F	*- F
16	1		*COVER REAR FLOOR UNDER CENTER	Not Necessary	229.90 F	*- F
17	1		*LENS & BODY ,REAR COMBINATION LAMP RH	Not Necessary	339.60 F	*- F
18	1		*LENS & BODY ,REAR COMBINATION LAMP LH	Not Necessary	339.60 F	*- F
19	1		*COVER ,REAR COMBINATION LAMP ,RH	Not Necessary	69.90 F	*- F
20	1		*COVER ,REAR COMBINATION LAMP ,LH	Not Necessary	69.90 F	*- F
21	1		*LENS & BODY ,REAR COMBINATION LAMP NO.2	Not Necessary	261.00 F	*- F
22	1		*LENS & BODY ,REAR COMBINATION LAMP NO.2	Not Necessary	261.00 F	*- F
23	1		*LAMP ASSY ,REAR RH	Not Necessary	293.60 F	*- F
24	1		*LAMP ASSY ,REAR LH	Not Necessary	293.60 F	*- F
25	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
26	1		*ANTENNA ELECTRICAL KEY	Not Necessary	72.00 F	*- F
27	1		*END PANEL SUB-ASSY BODY LOWER BACK	Not Necessary	651.00 F	*- F
28	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
29	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Not Necessary	913.60 F	*- F
30	1		*EMBLEM SUB-ASSY REAR	Not Necessary	47.90 F	*- F
31	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F
32	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F
33	1		*STRIDES LOGO	Not Necessary	7.80 F	*- F
34	1		*STICKER DECAL 65558888	Not Necessary	21.60 F	*- F
35	1		*SPOILER SUB-ASSY ,REAR	Not Necessary	1,575.40 F	*- F

F=Franchise part.

Total Parts (\$\$) **7,754.60** **749.03**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	1,098.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
7	TOWING CHARGE	New	56.00	0.00
Gross Labour Cost (\$\$)			2,190.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >