

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21013312/R1VF3E2

Date: 10/03/2022

REFERENCE

Insured/Claimant:	KHOO LAY KEONG,ANDREW	Policy No:	1900019101	
Date of Loss:	29/12/2021	Nature of Claim:	OD	Claim No: 9347228846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ8048D	Engine No:	G4FGJH723741
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5032377
Reg. Date:	21/03/2019 (Man. Year: 2018)	Odometer:	57493 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R15	Rear Tyre Size:	215/65 R15
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,577.80	4,785.00	1,792.80	27.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,310.00	4,870.00	1,440.00	22.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,887.80	9,655.00	3,232.80	25.08
+ GST 7.00/7.00% (S\$)	902.15	675.85	226.30	25.08
Nett Amount (S\$)	13,789.95	10,330.85	3,459.10	25.08

INSPECTION

Date of Assignment:	30/12/2021	
Date Inspected:	30/12/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR NUMBER PLATE WITH CASING	Scratched	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-RR BUMPER	Deformed	651.00 FL	*651.00 FL
4	1		*COVER-RR BUMPER LWR	Cracked	241.00 FL	*241.00 FL
5	1		*COVER-RR BUMPER UNDER, LH	Not Necessary	33.00 FL	*- FL
6	1		*COVER-RR BUMPER FOG LAMP, LH	Not Necessary	19.00 FL	*- FL
7	1		*COVER-RR BUMPER FOG LAMP, RH	Cracked	19.00 FL	*19.00 FL
8	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
9	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
10	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
11	1		*BEAM-RR BUMPER	Cracked	318.00 FL	*318.00 FL
12	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
13	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
14	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
15	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
16	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
17	1		*BRACKET-RR BEAM LWR, CTR	Cracked	6.00 FL	*6.00 FL
18	2		*BRACKET-RR BEAM LWR MTG	Cracked	12.00 FL	*6.00 FL
19	1		*COVER-RR BUMPER UNDER, RH	Not Necessary	33.00 FL	*- FL
20	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
21	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
22	1		*PANEL ASSY-BACK	Bent	324.00 FL	*324.00 FL
23	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FL	*- FL
24	1		*PANEL ASSY-TRUNK LID	Bent	1,297.00 FL	*1,297.00 FL
25	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	97.00 FL	*- FL
26	1		*HINGE ASSY-TRUNK LID, RH	Bent	97.00 FL	*97.00 FL
27	1		*W/STRIP-TRUNK LID OPNG	Twisted	100.00 FL	*100.00 FL
28	1		*LATCH ASSY-TRUNK LID	Cracked	112.00 FL	*112.00 FL
29	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
30	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
31	1		*EMBLEM CERATO	Necessary	28.00 FL	*28.00 FL
32	1		*LAMP ASSY-CENTER GARNISH	Cracked	690.00 FL	*690.00 FL
33	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	608.00 FL	*- FL
34	1		*LAMP ASSY-REAR COMB INSIDE, RH	Cracked	608.00 FL	*608.00 FL
35	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Not Necessary	675.00 FL	*- FL
36	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cracked	675.00 FL	*675.00 FL
37	10		*CLIPS (Supplementary)	Necessary	10.00 FL	*10.00 FL
38	2		*GROMMET ASSY-SCREW (Supplementary)	Necessary	4.00 FL	*4.00 FL
39	1		*PLUG-DRAIN HOLE (Supplementary)	Necessary	5.00 FL	*5.00 FL
40	6		*FASTENER (Supplementary)	Necessary	6.00 FL	*6.00 FL
41	1		*PANEL ASSY-RR COMB LAMP HSG, RH (Supplementary)	Bent	135.00 FL	*135.00 FL
42	1		*PROTECTOR, HEAT REAR (Supplementary)	Bent	136.00 FL	*136.00 FL
43	1		*K3 BOOT LID SPOILER (Supplementary)	Necessary	211.00 FS	*211.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,152.00	5,911.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,574.20	1,126.00
Total Parts (\$\$)	6,577.80	4,785.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, RR END PNL & BOOTLID. REPAIR RHR FENDER, LHR FENDER & RR FLR PNL	New	2,800.00	1,600.00
2	RESPRAY RR BUMPER, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER & RHR FENDER	New	2,100.00	2,100.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM	New	120.00	120.00
7	REMOVE & REFIT REVERSE SENSOR	New	80.00	60.00
8	SUPPLY REVERSE SENSOR	New	220.00	0.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
10	SUPPLY BODY PNL SEALANT	New	40.00	40.00
11	SUPPLY C&C BADGE	New	40.00	40.00
12	REPAIR QUARTER PANEL & TAIL LAMP PANEL (Supplementary)	New	400.00	400.00
13	FLOOR PULLING REAR CHASSIS (Supplementary)	New	200.00	200.00
Gross Labour Cost (\$\$)			6,310.00	4,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >