



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/KHOO LAY KEONG, ANDREW
	Reg No/Reg Date	SMJ8048D / 21/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5032377
	Engine No	G4FGJH723741
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	29/12/2021/ 18:48	BLE	261 / Edwin Caina	44837		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER , RR END PNL & BOOTLID @400 REPAIR RHR FENDER , LHR FENDER & RR FLR PNL							1600 2800.00
E PNT98000 RESPRAY RR BUMPER , RR END PNL , RR FLR PNL , BOOTLID , @350 LHR FENDER & RHR FENDER							2100.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT							120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET							120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING							50.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR							60 80.00
M SUNDRY SUPPLY REVERSE SENSOR							? 220.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							40.00
M SUNDRY SUPPLU BODY PNL SEALANT							40.00
M SUNDRY SUPPLY C&C BADGE							40.00
M SUNDRY Sundries							20.00
M	COVER-RR BUMPER			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR			1.00	241.00	20.00	192.80
M	COVER-RR BUMPER UNDER, LH			1.00	33.00	20.00	26.40
M	COVER-RR BUMPER FOG LAMP, LH			1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP, RH			1.00	19.00	20.00	15.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/KHOO LAY KEONG, ANDREW
	Reg No/Reg Date	SMJ8048D / 21/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5032377
	Engine No	G4FGJH723741
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	29/12/2021/ 18:48	BLE	261 / Edwin Caina	44837
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE T/SIGNAL, LH X		1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH CR ?		1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS ?		1.00	207.00	20.00	165.60
M BEAM-RR BUMPER CR / photo		1.00	318.00	20.00	254.40
M STAY-RR BUMPER LH ?		1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH ?		1.00	65.00	20.00	52.00
M ANTENNA ASSY-SMARTKEY ?		1.00	46.00	20.00	36.80
M BRACKET-RR BEAM UPR MTG, LH ?		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH ?		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR ?		1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG ?		2.00	6.00	20.00	9.60
M COVER-RR BUMPER UNDER, RH ?		1.00	33.00	20.00	26.40
M BRACKET ASSY-RR BPR SIDE UPR, ?		1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR, R ?		1.00	31.00	20.00	24.80
M PANEL ASSY-BACK CR		1.00	324.00	20.00	259.20
M TRIM ASSY-RR TRANSVERSE CR		1.00	41.00	20.00	32.80
M PANEL ASSY-TRUNK LID CR		1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID, LH ?		1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID, RH ?		1.00	97.00	20.00	77.60
M W/STRIP-TRUNK LID OPNG CR		1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID ?		1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID ?		1.00	40.00	20.00	32.00
M LOGO ASSY-KIA SUB CR		1.00	32.00	20.00	25.60
M EMBLEM-CERATO CR		1.00	28.00	20.00	22.40
M LAMP ASSY-CENTER GARNISH CR		1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE, LH X		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE, RH CR		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, LH X		1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE, RH CR		1.00	675.00	20.00	540.00

SURVEYOR NAME: Rasul-Hp 90510068SURVEYOR SIGNATURE: Rasul

Confirm & accepted by

DATE: 30/12/21 @ 1500REMARKS: 8 daysEXCESS: TBA / REPAIRRepair before print

Authorized signatory and company stamp

Nett	11,840.00
7% GST on	828.80
Total Payable	12,668.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.