

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 2697A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE WINDOW GLASS MOULDING	NECESSARY	120.00	120.00
1	TAILGATE	DENTED	1,840.00	1,300.00
1	TAILGATE WEATHERSTRIP	NOT DAMAGED	335.00	-
1	TAILGATE HINGE LH	NOT DAMAGED	125.00	-
1	TAILGATE HINGE RH	NOT DAMAGED	125.00	-
1	TAILGATE LOCK	NOT DAMAGED	475.00	-
1	TAILGATE TOYOTA LOGO	NECESSARY	90.00	68.40
1	TAILGATE COROLLA EMBLEM	NECESSARY	75.00	48.00
1	TAILGATE HYBRID EMBLEM	NOT DAMAGED	75.00	-
1	TAILGATE LAMP LH	NOT DAMAGED	890.00	-
1	TAILGATE LAMP RH	NOT DAMAGED	890.00	-
1	TAILGATE INNER TRIM BOARD	NOT DAMAGED	958.00	-
10	TAILGATE INNER TRIM BOARD CLIP	NOT DAMAGED	50.00	-
1	TAILGATE INNER HANDLE	NOT DAMAGED	120.00	-
1	REAR BUMPER	BROKEN	523.50	523.50
1	REAR BUMPER LOWER LIP	DENTED	445.80	445.80
1	REAR BUMPER RETAINER LH	NECESSARY	110.00	75.40
1	REAR BUMPER RETAINER RH	NECESSARY	110.00	75.40
1	REAR BUMPER SENSOR	SHORT CIRCUIT	550.00	100.00
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	458.00	-
10	REAR BUMPER CLIP	NECESSARY	50.00	30.00
1	REAR BUMPER REFLECTOR LH	NOT DAMAGED	100.00	-
1	REAR BUMPER REFLECTOR RH	NOT DAMAGED	100.00	-
1	TAIL LAMP RH	BROKEN	1,100.00	800.00
1	TAIL LAMP LH	BROKEN	1,100.00	800.00
1	END PANEL	DENTED	925.50	750.00
1	END PANEL TRIM	BROKEN	328.50	328.50
1	REVERSE CAMERA	NOT DAMAGED	750.60	-
	LESS 25% DISCOUNT		-3,204.98	-1,366.25
			9,614.92	4,098.75

Report Ref No. CS/AGI21013313/Bqf3n2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR NUMBER PLATE & HOLDER (SN)	NOT DAMAGED	80.00	-
1	CERAMIC COATING (SN)	NOT NECESSARY	800.00	-
			1,040.00	40.00
	<u>LABOUR</u>			
	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS.		1,400.00	600.00
	TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE.		120.00	80.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT ALL SENSOR & REVERSE CAMERA.		300.00	60.00
	TO REMOVE & REPLACE REAR WINDSCREEN.		160.00	120.00
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	80.00	-
	TO SPRAY PAINTING ON THE AFFECTED AREA.		1,200.00	600.00
			3,710.00	1,460.00
	GRAND TOTAL		14,364.92	5,598.75

RECOMMENDED COST OF LUMP SUM REPAIRS		4,450.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21013313/Bqf3n2



**Automotive Assessor** 



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.