

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 09 Mar 2022

**Preliminary Advice**

Insured Vehicle No	:	SKF3229B		
TP Vehicle No	:	GBK9363L	Accident Date	: 21/12/2021
Make	:	TOYOTA HIACE	Assignment Date	: 30/12/2021
Date of Inspection	:	22/02/2022	Est. Duration of Repair	: 7
Inspection At	:	A T AUTO CONSULTANT (HQ) B/113 TECK WHYE LANE, #05-650 SINGAPORE 680113		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 19,471.75
Revised Amount	:	S\$ 6,811.05
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 6,811.05
Lump Sum Repair		: S\$ 5,400.00

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- ( ) The vehicle is economical for repair
  - ( ) The vehicle is not economical for repair
  - ( ) Part-by-Part repair
  - (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.