

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG21013316/KTF3N2**Date:** 13/05/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29145679AL2
<b>Claimant Vehicle No :</b>	GBK9363L	<b>Insured Vehicle No :</b>	SKF3229B
Date of Loss:	21/12/2021	Nature of Claim:	TP
		Claim No:	639418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBK9363L</b>		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KDB064043
Reg. Date:	25/01/2021 (Man. Year: 2020)	Chassis No:	JTFHT02P400250899
Colour:	Black	Odometer:	37954 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	West Lake 9 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,421.75	4,531.05	8,890.70	66.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,050.00	2,280.00	3,770.00	62.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,471.75</b>	<b>6,811.05</b>	<b>12,660.70</b>	<b>65.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>19,471.75</b>	<b>5,400.00</b>	<b>14,071.75</b>	<b>72.27</b>

INSPECTION

Date of Assignment:	30/12/2021		
Date Inspected:	22/02/2022	Inspected At:	A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650 Singapore 680113
Estimated Period of Repair:	7.0 days		

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9363L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	980.00 FL	*496.40 FL
2	1		*FRONT BUMPER LOWER GRILLE	Serviceable	325.00 FL	*- FL
3	1		*FOG LAMP GARNISH	Distorted	98.00 FL	*98.00 FL
4	1		*HEADLAMP RH	Cut	950.00 FL	*903.20 FL
5	1		*HEADLAMP BRACKET RH	Distorted	35.00 FL	*35.00 FL
6	1		*FRONT WINDSCREEN (CRACKED)	Not Consistent With The Impact	1,612.00 FL	*- FL
7	1		*FRONT WINDSCREEN MOULDING	Not Necessary	325.00 FL	*- FL
8	1		*FRONT PANEL	Repair	911.00 FL	*- FL
9	1		*FRONT PANEL EMBLEM TOYOTA	Not Necessary	76.00 FL	*- FL
10	1		*FRONT CORNER APRON RH	Bent	123.00 FL	*123.00 FL
11	1		*FRONT GRILLE CENTER OUTER	Repair	456.00 FL	*- FL
12	1		*FRONT GRILLE CENTER REAR SUPPORT	Repair	356.00 FL	*- FL
13	1		*FRONT REINFORCEMENT TOP	Repair	452.00 FL	*- FL
14	1		*FRONT REINFORCEMENT LOWER	Repair	655.00 FL	*- FL
15	1		*FRONT REINFORCEMENT LINK BRACKET RH	Repair	112.00 FL	*- FL
16	1		*FRONT REINFORCEMENT TOP REAR BRACKET RH	Repair	165.00 FL	*- FL
17	1		*RADIATOR TOP SUPPORT PANEL	Repair	561.00 FL	*- FL
18	1		*AIR INTAKE RESONATOR	Cracked	389.00 FL	*302.60 FL
19	1		*WIRE TERMINAL BOX	Serviceable	98.00 FL	*- FL
20	1		*FRONT DOOR RH	Bent	1,529.00 FL	*1,318.10 FL
21	1		*B PILLAR PANEL (NPA)	Repair	0.00 FL	*- FL
22	1		*MID SLIDING DOOR	Bent	2,496.00 FL	*1,545.10 FL
23	1		*REAR FENDER RH	Repair	1,568.00 FL	*- FL
24	1		*REAR BUMPER	Repair	736.00 FL	*- FL
25	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	66.00 FL	*- FL
26	1		*REAR APRON CORNER PANEL RH	Serviceable	156.00 FL	*- FL
27	1		*TAIL LAMP RH	Serviceable	339.00 FL	*- FL
28	1		*FRONT DOOR SIDE STEP	Dented/Cut	120.00 FL	*120.00 FL
29	1		*FRONT WHEEL SIDE MUDFLAP	Cut	60.00 FL	*60.00 FL
30	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
31	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
32	2		*FRONT/REAR RIM COVER RH	Dented/Cut	160.00 FS	*160.00 FS
33	1		*FRONT PANEL COMPANY LOGO	Not Necessary	160.00 FS	*- FS
34	1		*FRONT WINDSCREEN COMPANY LOGO	Not Necessary	160.00 FS	*- FS
35	1		*FRONT DOOR COMPANY STICKER X2	Necessary	140.00 FS	*100.00 FS
36	1		*MID SLIDING DOOR COMPANY LOGO	Necessary	320.00 FS	*220.00 FS
37	1		*REAR FENDER COMPANY STICKER	Necessary	360.00 FS	*250.00 FS
38	1		*SET FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*SET AIRCON GAS	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)		17,359.00	5,781.40
- List Item Discount on L Items 25.00/25.00% (\$\$)		3,937.25	1,250.35
Total Parts (\$\$)		13,421.75	4,531.05
Report was unsubmitted during this print-out.			

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	2,400.00	1,000.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	3,000.00	1,200.00
3	WIRING CHARGES	New	100.00	20.00
4	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	150.00	60.00
5	REMOVE/REFIX REAR DECK RACKING TO FACILITATE REPAIR	New	400.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>6,050.00</b>	<b>2,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >