

ASS. REQ. BY:

REF:

MSG / 21013316/k+

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/Nr:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/A / S/Rim / STD A/Rim or

Tyre Size:

R: B.S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 Email:atautoconsultant@gmail.com

Co. Reg. No. : 53368526E

Date of Estimate: 27.12.2021

Vehicle No: GBK9363L

Owner: BRAVEHEART@SRM SERVICES PTE LTD

Date of Accident: 21.12.2021

Make & Model: TOYOTA HIACE VAN TURBO SDR MT

Chassis No : JTFHT02P400250899

ESTIMATE FOR ACCIDENT VEHICLE NO ~~GBK6668T~~ GBK9363L

PARTS

- 1 1 Front bumper
- 2 1 Front bumper lower grille
- 3 1 Fog lamp garnish
- 4 1 Headlamp RH
- 5 1 Headlamp bracket RH
- 6 1 Front windsceen
- 7 1 Front windscreen moulding
- 8 1 Front panel
- 9 1 Front panel emblem "Toyota"
- 10 1 Front corner apron RH
- 11 1 Front grille center outer
- 12 1 Front grille center rear support
- 13 1 Front reinforcement top
- 14 1 Front reinforcement lower
- 15 1 Front reinforcement link bracket RH
- 16 1 Front reinforcement top rear bracket RH
- 17 1 Radiator top support panel
- 18 1 Air intake resonator
- 19 1 Wire terminal box
- 20 1 Front door RH
- 21 1 B pillar panel (repair)
- 22 1 Mid sliding door
- 23 1 Rear fender RH
- 24 1 Rear bumper
- 25 1 Rear bumper side retainer RH
- 26 1 Rear apron corner panel RH
- 27 1 Tail lamp RH

AT Auto Consultant
The Repair of the following:
• To remove damaged parts during survey
• To display damaged parts during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Subsequently, items must be reviewed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

SUB TOTAL

LESS 25%

DISCOUNTED SUB TOTAL

R1 \$980.00 ✓
S1 \$325.00 X
D1 \$98.00 ✓
G1 \$950.00 ✓
\$35.00 ?
(n.c) cm \$1,612.00 X
na \$325.00 X
n \$911.00 X
na \$76.00 X
R1 \$123.00 ✓
n \$456.00 X
n \$356.00 X
\$452.00 ?
\$655.00 ?
\$112.00 ?
\$165.00 ?
n \$561.00 X
\$389.00 ?
\$98.00 ?
R1 \$1,529.00 ✓
\$0.00
R1 \$2,496.00 ✓
n \$1,568.00 X
n \$736.00 X
n \$66.00 X
S1 \$156.00 X
S1 \$339.00 X

\$15,569.00

\$3,892.25

\$11,676.75

(28) Front door side step \$120 n/c

(29) Front wheel side mudflap \$60 n/c

Not Authorized
L1 Emp 3
Penny After Pains
Today

S. NETT ITEM

- 1 1set Front bumper clips
- 2 1set Front grille clips
- 3 2 Front/rear rim cover RH
- 4 1 Front panel company logo
- 5 1 Front windscreen company logo
- 6 1 Front door company sticker x 2
- 7 1 Mid sliding door company logo
- 8 1 Rear fender company sticker
- 9 1set Front windscreen sealant
- 10 1set Aircon gas

SUB TOTAL
 LESS 0 %
 DISCOUNTED SUB TOTAL

@ \$80.00
 \$50.00
 \$30.00 X
 \$160.00
 \$160.00 X
 \$160.00 X
 \$140.00 100%
 \$320.00 220%
 \$360.00 250%
 \$80.00 X
 \$150.00 X
 \$1,610.00
 \$0.00
 \$1,610.00

LABOUR

- 1 Panel beating for replace and repair affected parts
- 2 Spray painting on accident areas
- 3 Wiring charges
- 4 Apply undercoating to above affected areas
- 5 Remove/refix rear deck racking to facilitate repair

SUB TOTAL (LABOUR)

100%
 \$2,400.00
 \$3,000.00 1200%
 \$100.00 20%
 \$150.00 60%
 \$400.00 X
 \$6,050.00

SUB TOTAL (PARTS)

\$11,676.75

S. NETT (PARTS)

\$1,610.00

SUB TOTAL (LABOUR)

\$6,050.00

ESTIMATED GRAND TOTAL

\$19,336.75

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: